



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 8873H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	250.00	-
1	HANDLE BAR END (CONSISTENT)	NOT NECESSARY	120.00	-
1	SET MIRROR (CONSISTENT)	SCRATCHED	120.00	80.00
1	HANDLE GUIDE (CONSISTENT)	CUT	150.00	120.00
1	CRASH BAR (CONSISTENT)	TO REPAIR SEE LABOUR	320.00	-
1	REAR KEY LOCK (CONSISTENT)	MISSING	180.00	120.00
1	REAR FAIRING COVER (CONSISTENT)	CRACKED	250.00	250.00
1	REAR NUMBER PLATE (CONSISTENT)	TO REPAIR SEE LABOUR	30.00	-
1	REAR BOX (CONSISTENT)	MISSING	380.00	280.00
1	FRONT LEFT FOOTREST (CONSISTENT)	CUT	150.00	60.00
1	REAR LEFT FOOTREST (CONSISTENT)	CUT	120.00	60.00
1	REAR SIGNAL LIGHT (CONSISTENT)	CUT	180.00	90.00
	LESS 10% DISCOUNT		-	-106.00
			2,250.00	954.00
	<b><u>LABOUR</u></b>			
	FORK ALIGNMENT.	NOT NECESSARY	300.00	-
	LABOUR. INCLUSIVE OF THE REPAIR OF CRASH BAR AND REAR NUMBER PLATE.		500.00	200.00
			800.00	200.00
	<b>GRAND TOTAL</b>		<b>3,050.00</b>	<b>1,154.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>900.00</b>

Report Ref No. CS/ASM22007825/Gcy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.