

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007826/APA3Q2**Date:** 20/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100365794
Claimant Vehicle No :	SKH7491Y	Insured Vehicle No :	SKM3971D
Date of Loss:	12/08/2022	Nature of Claim:	TP
		Claim No:	6865400467SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH7491Y	Engine No:	27195231042249
Make & Model:	MERCEDES-BENZ C180K, 1.8 (A)	Chassis No:	WDD2040462A136084
Reg. Date:	28/05/2008 (Man. Year: 2008)	Odometer:	168368 km
Colour:	Blue		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,309.60	10,614.80	5,694.80	34.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,560.00	1,970.00	55.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,839.60	12,174.80	7,664.80	38.63
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	19,839.60	8,800.00	11,039.60	55.64
+ GST 7.00/7.00% (S\$)	1,388.77	616.00	772.77	55.64
Nett Amount (S\$)	21,228.37	9,416.00	11,812.37	55.64
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		10,478.00		

INSPECTION

Date of Assignment:	15/08/2022	Inspected At:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Date Inspected:	15/08/2022		
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,201.00 FL	*1,201.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	587.00 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	344.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	84.00 FL	*84.00 FL
5	1		*FRONT BUMPER CENTER BRACKET	Not Necessary	87.00 FL	*- FL
6	1		*FRONT BUMPER CHROME MOULDING LH	Not Necessary	64.00 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	434.00 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP OUTER GARNISH LH	Not Necessary	324.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	198.00 FL	*- FL
10	1		*FRONT BUMPER CENTER MOULDING	Not Necessary	164.00 FL	*- FL
11	1		*FRONT GRILLE	Not Necessary	695.00 FL	*- FL
12	1		*FRONT GRILLE LOGO	Not Necessary	143.00 FL	*- FL
13	1		*FRONT GRILLE LOGO BASE	Not Necessary	215.00 FL	*- FL
14	1		*BONNET	Not Necessary	1,268.00 FL	*- FL
15	1		*BONNET HINGE LH	Not Necessary	174.00 FL	*- FL
16	1		*FRONT HEADLAMP LH	Cut	1,045.00 FL	*1,045.00 FL
17	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	189.00 FL	*- FL
18	1		*FRONT FENDER LH	Dented	652.00 FL	*652.00 FL
19	1		*FRONT FENDER INNER COWLING LH	Torn	187.00 FL	*187.00 FL
20	1		*FRONT LOWER ARM (REAR) LH	Bent	669.00 FL	*669.00 FL
21	1		*FRONT LOWER ARM (FRONT) LH	Bent	774.00 FL	*774.00 FL
22	1		*FRONT UPPER ARM LH	Bent	696.00 FL	*696.00 FL
23	1		*FRONT KNUCKLE ARM LH	Damaged	689.00 FL	*689.00 FL
24	1		*FRONT KNUCKLE ARM BEARING LH	Damaged	460.00 FL	*460.00 FL
25	1		*FRONT SHOCK ABSORBER LH	Bent	672.00 FL	*672.00 FL
26	1		*FRONT SPORT RIM LH	Cut	900.00 FS	*500.00 FS
27	1		*FRONT TYRE LH	Not Necessary	380.00 FS	*- FS
28	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*FRONT FENDER INNER COWLING CLIPS LH	Necessary	60.00 FS	*30.00 FS
30	1		*STEERING RACK & PINION	Bent	3,761.00 FL	*3,761.00 FL
31	1		*ANTI ROLL BAR	Not Necessary	486.00 FL	*- FL
32	1		*LH ANTI ROLL BAR LINK	Bent	282.00 FL	*282.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,964.00	11,732.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,654.40	1,117.20
Total Parts (\$\$)	16,309.60	10,614.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,400.00	600.00
2	LABOUR FOR SPRAYPAINTING	New	1,200.00	500.00
3	WIRING CHECK	New	80.00	30.00
4	LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE	New	400.00	300.00
5	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	50.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
			Gross Labour Cost (S\$)	1,560.00
			3,530.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >