

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22007829/Gvcm4		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	20-10-2022		
				INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	FBS 3078H		nspected	SHC 2528X	
	Policy No.			age (\$)	0.00	
	Claim No.	MT/1184709-002	Exces		0.00	
	Assign From		Assigi		15/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI AE IONIQ HEV 1.6	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2018	
	Chassis No.	KMHC851CVKU106581	Colou	r	BLUE	
	Odometer -		Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/08/2022	Inspec	tion Date	15/08/2022	
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					