

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC22007839/Gqy3m4	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	29/08/2022	
			Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 9463H	Veh. Inspected	GZ 3637Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	21/22/22/VC00/026156	Excess (\$)	0.00	
	Assign From	ONG LI LI	Assign Date	16/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA REGIUS 2.5	c.c	2494	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	KDH2000012974	Colour	WHITE	
	Odometer	465629 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15	OHTSU	6 mm	
	L/H Front Tyre	195 R15	OHTSU	6 mm	
	R/H Rear Tyre	195 R15	OHTSU	6 mm	
	L/H Rear Tyre	195 R15	OHTSU	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S REAR PORTION.			
5.	General Information				
	Accident Date	15/08/2022	Inspect Date / Time	17/08/2022 ( 02:30 PM )	
	Survey held at	TAN ENG HUAT MOTOR			
		BLK 6 DEFU LANE 10 #01-556 . SINGAPORE 539187			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22007839/Gqy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor