

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007840/ANY3Q2**Date:** 30/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00020032201

Claimant Vehicle No : GBE345E **Insured Vehicle No :** XD294M

Date of Loss: 16/08/2022 Nature of Claim: TP Claim No: SNM22D205700/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE345E**

Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2539758

Reg. Date: 21/08/2015 (Man. Year: 2000) Chassis No: KDH2015018403

Colour: Silver Odometer: 113682 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Transway 6 mm Rear Left Side: Transway 6 mm

Front Right Side: Transway 6 mm Rear Right Side: Transway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,380.65	5,072.07	3,308.58	39.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,530.00	1,250.00	44.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,160.65	6,602.07	4,558.58	40.85
Approved Total (Overridden) (\$\$)		5,200.00		
(\$\$)	11,160.65	5,200.00	5,960.65	53.41
+ GST 7.00/7.00% (\$\$)	781.25	364.00	417.25	53.41
Nett Amount (\$\$)	11,941.90	5,564.00	6,377.90	53.41

INSPECTION

Date of Assignment: 16/08/2022

Date Inspected: 17/08/2022 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2022)
Parts:	213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE345E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	548.30 FL	*- FL
2	1		*FRONT BUMPER LH RETAINER	Not Necessary	142.80 FL	*- FL
3	1		*FRONT LH DOOR	Dented	1,687.10 FL	*1,687.10 FL
4	1		*FRONT LH DOOR ARCH SEAL RUBBER	Not Necessary	55.00 FL	*- FL
5	1		*FRONT LH DOOR GLASS	Cut	535.70 FL	*535.70 FL
6	1		*FRONT LH DOOR GLASS CHANNEL SEAL	Not Necessary	133.60 FL	*- FL
7	1		*FRONT LH DOOR GLASS CHANNEL SEAL BRACKET	Not Necessary	72.00 FL	*- FL
8	1		*FRONT LH DOOR INNER PLASTIC SEAL COVER	Not Necessary	35.00 FL	*- FL
9	1		*FRONT LH DOOR MECHANISM LOCK	Damaged	574.80 FL	*365.00 FL
10	1		*FRONT LH DOOR OUTER HANDLE	Cut	188.10 FL	*188.10 FL
11	1		*FRONT LH DOOR OUTER HANDLE KNOB COVER	Cut	18.10 FL	*18.10 FL
12	1		*FRONT LH DOOR OUTER MOULDING	Cut	99.00 FL	*99.00 FL
13	2		*FRONT LH DOOR RUBBER GUIDE STOPPER	Not Necessary	24.00 FL	*- FL
14	1		*FRONT LH DOOR SIDE MIRROR	Distorted	1,197.10 FL	*1,197.10 FL
15	1		*FRONT LH DOOR WEATHERSTRIP SEAL	Cut	230.10 FL	*230.10 FL
16	1		*FRONT LH HEADLAMP	Not Necessary	2,584.50 FL	*- FL
17	1		*LH CENTER PILLAR	Dented	425.80 FL	*425.80 FL
18	1		*LH SLIDING DOOR	Dented	1,916.10 FL	*1,722.00 FL
19	1		*LH SLIDING DOOR OUTER HANDLE	Cut	188.10 FL	*188.10 FL
20	1		*PETROL LID COVER	Repair	119.00 FL	*- FL
21	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*FRONT LH DOOR COMPANY DETAIL STICKER	Necessary	50.00 FS	*30.00 FS
23	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*LH CENTER PILLAR SEALANT	Necessary	100.00 FS	*50.00 FS
25	1		*SET LH SLIDING DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,074.20	6,736.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,693.55	1,664.03
Total Parts (\$\$)	8,380.65	5,072.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING (TO FR)	New	60.00	30.00
2	TO REMOVE REINSTALL PETROL TANK (TO FR)	New	100.00	0.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	60.00
4	TO TRANSFER DOOR GLASS ,REGULATOR GEAR MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	200.00	80.00
5	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
6	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
Gross Labour Cost (\$\$)			2,780.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >