

ASS. REC. BY:

REF:

C72/ 22007842/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMQ 8435H Yr Regn: 12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Alphard A) Wagon C.C. 2493

Colour

n. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AY1430. 0089381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal.

S mm

R/Bal.

S mm

L/Bal.

S mm

L/Bal.

S mm

D.O.A.

14/8/22

D.O.I.

16/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear W/door Shattered

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Battery flat, GIA & Est not ready

19/10/11 Dr @ 7200 Cahr

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Washed
11 Pcs @ 7200/-
Respray After Paint
6 days

LM AUTO SOLUTION PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C,

#01-12 Singapore 575645

Email: admin@lmautosolution.com

Tel: 90162222

VEHICLE NUM:

SMQ 8435 H

MAKE & MODEL:

TOYOTA ALPHARD

MILEAGE:

ENGINE NUM:

CHASSIS NUM:

ATTN:					
NO.	DESCRIPTION - PARTS	QTY	PRICE		
1	TAIL GATE 2040.50	1	\$ 2,264.80	✓	
2	TAIL GATE GLASS 1301- Shatter	1	\$ 1,455.00	✓	
3	TAIL GATE GLASS MOULDING	1	\$ 223.60	✓	
4	TAIL GATE CHROME 785.10	1	\$ 863.90	✓	
5	TAIL GATE LAMP LH + RH @ 1051.20	2	\$ 2,256.60	✓	
6	TAIL GATE CAMERA	1	\$ 679.20	X	
7	TAIL GATE OPENER SENSOR SWITCH	1	\$ 186.50	X	
8	TAIL GATE LOCK WITH MOTOR	1	\$ 846.50	X	
9	TAIL GATE EMBLEM - ALPHARD	1	\$ 121.30	—	
10	TAIL GATE EMBLEM - HYBRID	1	\$ 92.60	—	
11	TAIL GATE EMBLEM - E FOUR	1	\$ 84.10	✓	
12	TAIL GATE INNER TRIM	1	\$ 778.50	X	
13	TAIL GATE UPPER TRIM	1	\$ 326.40	X	
14	TAIL GATE SIDE TRIM LH + RH	2	\$ 466.80	✓	
15	REAR BUMPER 1605	1	\$ 2,288.30	✓	
16	REAR BUMPER RETAINER LH + RH	2	\$ 331.20	✓	
17	REAR BUMPER BRACKET LH + RH	2	\$ 345.80	X	
18	REAR BUMPER REFLECTOR LH + RH	2	\$ 329.60	X	
19	REAR BUMPER TOWING CAP	1	\$ 117.40	X	
20	REAR BUMPER CLIP [SET]	1	\$ 50.00	✓	
21	REAR BUMPER SENSOR	4	\$ 1,963.20	X	
22	REAR BUMPER SENSOR WIRE	1	\$ 191.30	X	
23	TAIL LAMP LH + RH	2	\$ 1,865.80	✓	
24	TAIL LAMP LOWER GARNISH LH + RH	2	\$ 615.80	X	
25	TAIL LAMP CLIP LH + RH	4	\$ 40.00	X	
26	REAR END PANEL 781.70	1	\$ 827.60	✓	
27	REAR END PANEL SENSOR	1	\$ 165.30	X	
28	REAR END PANEL TOP GARNISH	1	\$ 197.50	✓	
29	REAR FENDER RH	1	REPAIR		
30	REAR FENDER INNER TRIM RH	1	\$ 2,144.30	X	
SUBTOTAL			\$ 22,118.90		

	25%		\$	5,529.73	
	PARTS TOTAL		\$	16,589.18	
	SPECIAL NETT	QTY	PRICE		
1	REAR BUMPER LOWER SPOILER ASSY X NN	1	\$	2,800.00	X
	SPECIAL NETT 1		\$	2,800.00	
	LABOUR	QTY	PRICE		
1	TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$	1,400.00	600l
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$	1,000.00	800l
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$	120.00	60l
4	TO R & R TAIL GATE GLASS	1	\$	120.00	✓
5	TO R & R TAIL GATE MECHANISM	1	\$	180.00	60l
6	TO R & R REAR LUGGAGE COMPARTMENT,UPHOSTERY	1	\$	300.00	60l
7	TO R & R REVERSE SENSOR, CAMERA AND CHECK FUNCTION	1	\$	120.00	70l
	LABOUR TOTAL		\$	3,240.00	
	GRAND TOTAL COST		\$	22,629.18	

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: