

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22007852/UQY3M4**Date:** 08/09/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001960892
<b>Claimant Vehicle No :</b>	GBD8776Y	<b>Insured Vehicle No :</b>	SLN143E
Date of Loss:	13/08/2022	Nature of Claim:	TP
		Claim No:	281783

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBD8776Y</b>		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR1SDEB (M)	Engine No:	4P10B61216
Reg. Date:	26/06/2015 (Man. Year: 2015)	Chassis No:	FEA01BA10087
Colour:	White	Odometer:	190964 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,335.80	1,892.30	3,443.50	64.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	740.00	470.00	38.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,545.80</b>	<b>2,632.30</b>	<b>3,913.50</b>	<b>59.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,545.80</b>	<b>2,100.00</b>	<b>4,445.80</b>	<b>67.92</b>

**INSPECTION**

Date of Assignment:	17/08/2022	
Date Inspected:	17/08/2022	Inspected At: Liu's Brother Auto Workshop (HQ) 1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 08 Sep 2022)	
<b>Parts:</b>	N/A	mitsubishi canter 3.0 D FEA01BR1SDEB (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD8776Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH DOOR	Repair	1,995.00 F	*- FL	
2	1		*FRONT RH CORNER PANEL	Cracked	486.90 F	*408.21 FL	
3	1		*FRONT RH HEAD LAMP	Cracked	856.40 F	*620.25 FL	
4	1		*FRONT BUMPER	Bent	976.00 F	*780.90 FL	
5	1		*FRONT RH SIGNAL LAMP	Broken	324.30 F	*208.21 FL	
6	1		*FRONT RH BUMPER SIDE	Distorted	441.70 F	*303.00 FL	
7	1		*SET FRONT RH CORNER PANEL CLIPS	Not Necessary	28.00 FS	*- FS	
8	1		*FRONT DOOR ROC STICKER	Necessary	65.00 FS	*30.00 FS	
9	1		*FRONT SIDE LAMP O/S	Cracked	162.50 F	*162.50 FL	
					<b>Sub Total (\$\$)</b>	<b>5,335.80</b>	<b>2,513.07</b>
					<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	620.77
					<b>Total Parts (\$\$)</b>	<b>5,335.80</b>	<b>1,892.30</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	320.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	500.00	400.00
4	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,210.00</b>	<b>740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >