



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 2745H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR	BENT	280.00	175.00
1	SET HANDLE BAR BALANCER RH	GRAZED	24.00	24.00
1	SET HANDLE BAR GRIP RH	NOT NECESSARY	60.00	-
1	FRONT PANEL	CRACKED	115.00	115.00
1	SET FRONT VIEW MIRROR RH	GRAZED	160.00	160.00
2	BRAKE LEVER L/R @\$38.00	O/S GRAZED / BENT	76.00	38.00
1	FRONT CONSOLE PANEL	NOT NECESSARY	189.00	-
1	FRONT HEADLAMP STAY	MISALIGNED	58.00	58.00
1	FRONT HEADLAMP ASSY	CRACKED	860.00	499.00
2	FRONT BODY SIDE COWLING L/R @\$245.00	GRAZED	490.00	490.00
2	FRONT BODY SIDE PANEL L/R @\$195.00	CRACKED	390.00	390.00
2	FRONT LOWER SIDE MOLE COVER L/R @\$98.00	GRAZED	196.00	196.00
2	FRONT LOWER SIDE PANEL L/R @\$145.00	GRAZED / CRACKED	290.00	290.00
2	CENTER SIDE COVER L/R @\$190.00	CRACKED	380.00	380.00
1	FRONT SIGNAL LAMP LH	CRACKED	75.00	75.00
2	FRONT FORK TUBE L/R @\$298.00	BENT	596.00	596.00
1	LOWER FORK BRACKET	BENT	740.00	190.00
1	LOWER UNDER COVER	TORN	160.00	160.00
1	FRONT FENDER	GRAZED	145.00	145.00
1	FRONT INNER FENDER	NOT NECESSARY	210.00	-
1	FRONT WHEEL RIM	NOT NECESSARY	590.00	-
2	FOOTREST BOARD L/R @\$280.00	GRAZED	560.00	560.00
2	FOOTREST BOARD RUBBER MAT L/R @\$48.00	NOT NECESSARY	96.00	-
1	RADIATOR COVER	MISSING	84.00	84.00
2	REAR SIDE COVER L/R @\$180.00	GRAZED / CRACKED	360.00	360.00
1	REAR UNDER COVER	CRACKED	217.00	217.00
1	REAR CRANKCASE COVER	GRAZED	240.00	240.00
1	REAR AIR-CLEANER CASE COVER	GRAZED	160.00	160.00
1	REAR AIR-INTAKE COVER	MISSING	58.00	58.00

Report Ref No. CS3/ASM22004277/Gqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST MUFFLER PROTECTOR LESS 10% DISCOUNT	GRAZED	140.00 -799.90 7,199.10	140.00 -580.00 5,220.00
<u>SPECIAL NETT ITEMS</u>				
1	SET STEERING CONE UPPER / LOWER BEARING (SN)	NECESSARY	68.00	68.00
1	SET FRONT COWLING & COVER DECAL STICKER (SN)	NECESSARY	120.00	120.00
2	FORK OIL SEAL & DUCT COVER @\$34.00 (SN)	NECESSARY	68.00	68.00
1	BOT FORK OIL (SN)	NECESSARY	18.00	18.00
			274.00	274.00
<u>LABOUR</u>				
TOWING SERVICE CHARGE. (2 TRIPS)			80.00	80.00
TO STRAIGHTEN, REPAIR & REALIGN BODY FRAME.			480.00	250.00
TO CHECK WIRING, RE-CONNECTION, LIGHTING SYSTEM & RESET.			80.00	30.00
REPLACE, REALIGN & ADJUST ABOVE DAMAGED PARTS. CHECK WIRING, RE-CONNECTION & LIGHTING SYSTEM.			600.00	300.00
			1,240.00	660.00
GRAND TOTAL			8,713.10	6,154.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CS3/ASM22004277/Gqy3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.