

Dynasty Motor Pte Ltd

50 Bukit Batok Street 23 #01-24 Midview Building Singapore 659678

To : Patrick Pek

C/O 259B Compassvale Road

#09-623 Singapore 542259

Date : 24 February 2021

Tax Invoice : DYM/JRC6736/TP218494

Vehicle No : JRC 6736

Make : Yamaha 135 LC

Date Of Accident : 23.01.2021

PARTICULAR	Amount S\$
------------	------------

Front & Both Side Damaged

Parts replacement, straighten, check, balancing,
Alignment, Transportation And Labour, etc.

Lump-Sum repair cost as per surveyor report
recommendation -----

\$3,800.00

Singapore Dollars : Three Thousand Eight Hundred Only

Total \$

\$3,800.00 Nett


Dynasty Motor Pte Ltd



KTO Automobile Assessors

Reg. No : 52941122M

470 Segar Road #09-232 Singapore 670470 Email: ktoa@singnet.com.sg HP: 98505311

INVOICE

M/S: Patrick Pek
C/O Dynasty Motor Pte Ltd.
50 Bukit Batok Street 23 #01-24
Midview Building Singapore 659678

Invoice No : 21-08494

Invoice Ref : TP/DYM/JRC6736/8494

Date : 22 February 2021

DESCRIPTION	AMOUNT
For Services Rendered Inspection report fees inclusive of : Transportation & Photographs Thirty-Two (32) copies. Vehicle No : JRC 6736 Make/Model : Yamaha LC135	\$ 392.00
Singapore Dollars: Three Hundred Ninety Two Only	\$ 392.00

Cheques should be made payable to **KTO AUTOMOBILE ASSESSORS**. Please indicate our Invoice No. on the reverse of your cheque.

KTO AUTOMOBILE ASSESSORS

Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Patrick Pek
C/O Dynasty Motor Pte Ltd.
50 Bukit Batok Street 23 #01-24
Midview Building Singapore 659678

Date : 22 February 2021
Our Ref : TP/DYM/JRC6736/8494

REFERENCE PARTICULARS

Date of Accident : 23 January 2021
Date of Inspection : 28 January 2021

Type of Inspection : Third Party Claim
Date of Re-Inspn : ~

VEHICLE PARTICULARS

Registration No : JRC 6736
Make : Yamaha
Model : 135 LC
Year : 2015

Engine No : ~
Chassis No : ~
Odometer : 81398 km
Colour : Black/Orange

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Front brake : Affected
Rear brake : Serviceable

General Body Work : Good
Steering : Affected
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	: Maxxis	70/90-17	5 mm
Rear	: Maxxis	80/90-17	5 mm

GENERAL DESCRIPTION OF DAMAGES

The motorcycle sustained damage at the front & both side portion.

For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **\$3,800.00 nett** at lump sum basis. (Subject to GST if applicable).

Under normal circumstances, estimated period required for repairs : Five (5) working days.

Enclosed Thirty-Two (32) photographs depicting damage to the vehicle.

Inspection conducted at : Dynasty Motor Pte Ltd.
Kaki Bukit Synergy @ KB 25 Kaki Bukit Road 4 #01-82 Singapore 417800

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS						
A) SPARE PARTS	QTY	ASSESSED	ORIGINAL	REVISED		
	PC/SET	CONDITION	QUOTATION	QUOTATION		
1 Handle bar	1	Bent	\$ 85.00	\$ 85.00		
2 Handle bar bracket	1	Bent	\$ 87.00	\$ 87.00		
3 Handle bar balancer LH	1 set	Grazed	\$ 20.00	\$ 20.00		
4 Brake lever	1	Serviceable	\$ 28.00	~		
5 Front view mirror L/R	1 set	Broken/Grazed	\$ 160.00	\$ 160.00		
6 Front headlamp unit	1	Serviceable	\$ 158.00	~		
7 Front headlamp cowling	1	Serviceable	\$ 85.00	~		
8 Front panel	1	Cracked	\$ 150.00	\$ 150.00		
9 Front panel cover	1	Grazed	\$ 120.00	\$ 120.00		
10 Front signal lamp L/R @ \$95.00	2	Grazed	\$ 190.00	\$ 95.00		
11 Front signal lamp garnish	1	Cracked	\$ 105.00	\$ 105.00		
12 Front side top cover L/R @ \$80.00	2	LH only (Grazed)	\$ 160.00	\$ 80.00		
13 Front side fairing L/R @ \$260.00	2	Grazed	\$ 520.00	\$ 520.00		
14 Front side fairing bracket @ \$12.00	4	Bent	\$ 48.00	\$ 48.00		
15 Front side lower garnish L/R @ \$75.00	2	Grazed	\$ 150.00	\$ 150.00		
16 Front fork tube L/R @ \$240.00	2	Misaligned	\$ 480.00	\$ 480.00		
17 Lower fork bracket	1	Misaligned	\$ 220.00	\$ 220.00		
18 Front fender	1	Grazed	\$ 68.00	\$ 68.00		
19 Front sport rim	1	Warped	\$ 380.00	\$ 380.00		
20 Front wheel rim axle	1	Necessary	\$ 35.00	\$ 35.00		
21 Front brake disc	1	Warped	\$ 145.00	\$ 145.00		
22 Front footrest bar	1	Bent	\$ 157.00	\$ 157.00		
23 Gear shift pedal	1	Bent	\$ 68.00	\$ 68.00		
24 Front footrest bar rubber footpeg L/R	1 set	Torn	\$ 36.00	\$ 36.00		
25 Rear brake pedal	1	Bent	\$ 78.00	\$ 78.00		
26 Rear swing arm	1	Misaligned	\$ 415.00	\$ 415.00		
27 Rear arm shaft & brush	1 set	Necessary	\$ 48.00	\$ 48.00		
28 Rear exhaust muffler protector	1	Serviceable	\$ 95.00	~		
29 Rear side cover L/R @ \$195.00	2	LH only (Grazed)	\$ 390.00	\$ 195.00		
			\$ 4,681.00	\$ 3,945.00		
		Less 10%	\$ 468.10	\$ 394.50		
			\$ 4,212.90	\$ 3,550.50		
B) S/NETT ITEM						
30 Front rim bearing & seal	1 set	Necessary	\$ 40.00	\$ 40.00		
31 Front cowling 'Yamaha' emblem	1	Necessary	\$ 8.00	\$ 8.00		
32 Front side fairing L/R 'Yamaha' emblem	1 set	Necessary	\$ 16.00	\$ 16.00		
33 Fairing decal set	1 set	Necessary	\$ 58.00	\$ 58.00		
34 Steering cone bearing	1 set	Necessary	\$ 68.00	\$ 68.00		
35 Rear box	1	Grazed	\$ 220.00	\$ 220.00		
36 Rear box bracket L/R	1 set	Bent	\$ 120.00	\$ 120.00		
37 Fork oil seal & duct cover @ \$34.00	2	Necessary	\$ 68.00	\$ 68.00		
38 Fork oil	1	Necessary	\$ 30.00	\$ 30.00		
		Parts Total :	\$ 4,840.90	\$ 4,178.50		

C) LABOR CHARGES

39	Towing service charge (2 Trips)	\$	80.00	\$	80.00
40	To straighten & re-align front body frame.	\$	250.00	\$	180.00
41	Replace, repair, adjust & realign above damaged parts				
	Check, re-connection wiring & lighting system.	\$	450.00	\$	350.00
	Labour Total :	\$	780.00	\$	610.00
	Total Parts and Labour	\$	5,620.90	\$	4,788.50

FINAL LUMP SUM ADJUSTMENT

\$ 3,800.00

REMARKS

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$3,800.00 nett** corresponding to replacement of parts and labour charges. We now revert for your decision on the above claim.

Yours faithfully
KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser















