

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : MT/1184000-002 Date: 25th Aug 2022

Our Ref : CS/INC22007866/Kvy3e2

M/s Ntuc Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 Ntuc Trade Union House Singapore 189556 (The Motor Claims Department)

Attn: David Phua

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YP 1929J INSURED VEHICLE: SJY 6716D ACCIDENT ON 11/06/2022

Instruction was received to inspect the vehicle Reg. No. YP 1929J. The inspection was conducted on 17/08/2022 at the premises of M/s Systematic Airconditioning Pte Ltd, 29 Senoko Way, Singapore 758059.

The following vehicle information was recorded:

Registration Number : YP 1929J

Make/Model : Isuzu NQR75UL5A

Year of Registration : 2016 Body Colour : White

Chassis Number : JAAN1R75LG7100690

Engine Capacity : 5193 cc

Speedometer Reading : Not Available

The vehicle sustained damages at the n/s body and rear portion. The Estimated repair cost of such vehicle is \$\$94,495.45 (Sin Dollars: Ninety-Four Thousand Four Hundred Ninety-Five and Forty-Five Cents only.) (Include check items \$\$24,638.05Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "uneconomical Total Loss".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 65,000.00 - 75,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 1,804.00)

Nett Liability

S\$ 63,196.00 - 73,196.00

S\$ 63,196.00 - 73,196.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) (Include check items \$\$24,638.05Nett) S\$ 94,495.45

Nett Liability

S\$

94,495,45

(a) - (b) =

(S\$ 31,299.45 - 21,299.45)

The amount of estimated saving of S\$31,299.45 - 21,299.45 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK), MASME(USA), B Bus(Aust),MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA), AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.