

ASS. REC. BY:

REF: INC1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

GIA / PR Seen: _____

Est. Repairs: _____

Lum Sum: _____

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: Autline

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/8

Barker Plot, LTA rebate @ 1805.00

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Systematic Airconditioning Pte Ltd

29 Senoko Way Singapore 758059

Tel : 64847188 Fax: 64841334

GST No. 199800703G

Contact: Sha (64847188)

Email : shah@systematicaircon.com

EstimationTo: **NTUC INCOME INSURANCE CO-OPERATION LTD***Kennerth Hong @ HKAuto.com*

DATE:	11-Aug-22
D.O.A:	11-Jun-22
Your ref:	SJY6716D

Isuzu NQR75UL5A - YP1929J

No.	Description	Qty	Unit Price	Total
1	18ft Insulated Box : 5400mm (L) x 2200mm (H) x 2320 mm (W) - ext. size Box Specifications : -UV treated GRP Board for the exterior of the box. -Food-grade GRP Board for the interior of the box (comply with EU food standard.) -75mm thickness extruded XPS with a min. density of 40kg/m3 between the exterior and interior. -Interior light c/w switch. -External Aluminum Trimmings on the edges of the box. -Stainless Steel checker plate flooring. -Stainless steel doorframe at the rear & side of the box. -2 rear bi-fold doors and 2 side bi-fold doors both sides. -Stainless steel external locks c/w keys and stainless-steel door hinges. -Internal elec. with 12V light and 1 gang two-way switch. -Drainage outlet. -PVC Curtains.	1	\$ 31,700.00 <i>131/74/320</i>	\$ 31,700.00
2	Movable Partition c/w PVC curtains on both side of cent	1 <i>mu</i>	\$ 4,500.00	\$ 4,500.00
3	Refrigeration Equipment (Mono block) Model:DSC 5000 Cooling Temperature:0°C to -20°C Refrigeration capacity:5000 watts at 0°C	1	\$ 9,800.00	\$ 9,800.00
4	Refrigeration Equipment (Split) Model:DS 5000 Cooling Temperature:0°C to -20°C Refrigeration capacity:5000 watts at 0°C	1	\$ 9,800.00	\$ 9,800.00
5	Supply one (1) Tailgate w/ Aluminium Alloy Platform (2ton)	<i>1</i> 1	\$ 12,500.00	\$ 12,500.00
6	Supply ARTWORK for Ref Box	<i>1</i> 1	\$ 2,100.00	\$ 2,100.00
7	To dismantle and reinstall 18ft Refrigerated Box and Tailgate	1	\$ 2,500.00	\$ 2,500.00
COST FOR REF BOX & TAILGATE (BEFORE GST)				\$ 70,400.00

1	Front bumper	Bz	1	\$ 980.00	\$ 980.00	
2	Front Bumper inner Bracket support LH	Bz	1	\$ 110.00	\$ 110.00	
3	Front Bumper inner Bracket support RH	R	1	\$ 110.00	\$ 110.00	X
4	front Grille	N/S	1	\$ 568.00	\$ 568.00	
5	front grille clips	mc	6	\$ 10.00	\$ 60.00	
6	front manufact badge/Isuzu emblem	nn	1	\$ 280.00	\$ 280.00	X
7	Headlamp assy LH/RH	N/S CM	2	\$ 740.00	\$ 1,480.00	4
8	front Fog Lights	N/S my Bro	2	\$ 120.00	\$ 240.00	+
9	Front Signal Lamp Asy LH	Rv	1	\$ 467.00	\$ 467.00	
10	Front Signal Lamp Asy LH	Rv	1	\$ 467.00	\$ 467.00	X
11	LH corner panel	Pr	1	\$ 248.00	\$ 248.00	X
12	LH corner panel Clip	nn	4	\$ 10.00	\$ 40.00	X
13	front panel	R	1	\$ 590.00	\$ 590.00	X
14	front panel clips	nn	8	\$ 20.00	\$ 160.00	X
15	windscreen	CM	1	\$ 1,800.00	\$ 1,800.00	
16	windscreen seal	nn	1	\$ 182.00	\$ 182.00	
17	upper moulding	nn	1	\$ 308.00	\$ 308.00	
18	windscreen sealant	nn	1	\$ 50.00	\$ 50.00	X
19	wiper arm	nn	2	\$ 280.00	\$ 560.00	X
20	wiper link	nn	1	\$ 380.00	\$ 380.00	X
21	wiper	nn	2	\$ 50.00	\$ 100.00	X
22	wiper motor	nn	1	\$ 670.00	\$ 670.00	X
23	wiper nozzel	nn	1	\$ 80.00	\$ 80.00	X
24	wiper water hose	nn	1	\$ 48.00	\$ 48.00	X
25	mirror arm LH	nn	1	\$ 580.00	\$ 580.00	X
26	LH Side mirror	Bro	1	\$ 168.00	\$ 168.00	
27	Side mirror garnish	nn	1	\$ 60.00	\$ 60.00	X
28	LH Blind Spot mirror (round)	mi	1	\$ 110.00	\$ 110.00	
29	Front Brake Shoe LH/RH	nn	2	\$ 257.00	\$ 514.00	X
30	Front Brake Drum LH/RH	nn	2	\$ 778.00	\$ 1,556.00	X
31	Front Brake pump LH/RH	nn	4	\$ 267.00	\$ 1,068.00	X
32	Front Wheel Oil seal inner H/RH	nn	2	\$ 68.00	\$ 136.00	X
33	Front Wheel Oil Seal Outer H/RH	nn	2	\$ 78.00	\$ 156.00	X
34	Front Tyres Bolt and Nuts	3 12		\$ 45.00	\$ 540.00	
35	Front Wheel Bearing Inner LH/RH	nn	2	\$ 128.00	\$ 256.00	X
36	Front Wheel Bearing Outer LH/RH	nn	2	\$ 178.00	\$ 356.00	X
37	Rear Mudguard LH	Bz	2	\$ 580.00	\$ 1,160.00	
38	Rear Mudguard Flap LH	N/S	1 12	\$ 90.00	\$ 180.00	4
39	Tyre Rim	nn	4	\$ 780.00	\$ 3,120.00	
40	Tyre	nn	6	\$ 300.00	\$ 1,800.00	X
41	Rear Brake Shoes LH/RH	nn	2	\$ 278.00	\$ 556.00	X
42	Rear Brake Drum LH/RH	nn	2	\$ 778.00	\$ 1,556.00	X
43	Rear Brake pump LH/RH	nn	4	\$ 267.00	\$ 1,068.00	X
44	Rear Wheel Oil seal inner H/RH	nn	2	\$ 68.00	\$ 136.00	X
45	Rear Wheel Oil Seal Outer H/RH	nn	2	\$ 78.00	\$ 156.00	X
46	Rear Tyres Bolt and Nuts	nn	12	\$ 45.00	\$ 540.00	X
47	Front Wheel Bearing Inner LH/RH	nn	2	\$ 128.00	\$ 256.00	X
48	Front Wheel Bearing Outer LH/RH	nn	2	\$ 178.00	\$ 356.00	X
49	Cabin Door Frame LH	Bz	2 1	\$ 1,450.00	\$ 2,900.00	4
50	Cabin Door Hinge LH	R	2	\$ 189.00	\$ 378.00	X
51	Cabin Door interior frame LH		1	\$ 893.00	\$ 893.00	?
52	Cabin Door Rubber seal LH	N/S	1	\$ 278.00	\$ 278.00	
53	Cabin Door Glass LH	Photo	1	\$ 780.00	\$ 780.00	
54	Power window arm And motor LH	AT/nn	1	\$ 780.00	\$ 780.00	

55	Cabin Door lock LH	1	\$ 487.00	\$ 487.00
56	Cabin Door Handle LH	1	\$ 238.00	\$ 238.00
57	Cabin Door Steep LH	1	\$ 193.00	\$ 193.00
58	Cabin Door Signal Lamp LH	1	\$ 120.00	\$ 120.00
59	Cabin Aircon Condenser coil	1	\$ 680.00	\$ 680.00
60	Cabin Aircon condenser Fan Asy	1	\$ 480.00	\$ 480.00
61	Cabin Aircon Blower	1	\$ 780.00	\$ 780.00
62	Cabin Aircon Discharge Hose	4	\$ 420.00	\$ 1,680.00
63	Cabin Aircon Suction Hose	1	\$ 420.00	\$ 420.00
64	Cabin Aircon 134A gas	1	\$ 110.00	\$ 110.00
65	Brake Oil Hose	1	\$ 128.00	\$ 128.00
66	Clutch Oil Hose	1	\$ 128.00	\$ 128.00
67	Clutch oil/ Brake Oil	3	\$ 60.00	\$ 180.00
68	Radiator Tank	1	\$ 780.00	\$ 780.00
69	Radiator upper hose	1	\$ 98.00	\$ 98.00
70	Radiator lower hose	1	\$ 90.00	\$ 90.00
71	Steering link	1	\$ 580.00	\$ 580.00
72	To tow accident vehicle to workshop by normal towing	1	\$ 250.00	\$ 250.00
73	LABOUR TO REMOVE AND INSTALL FRONT WINDSCREEN. PANEL BEAT, REPLACEMENT OF PARTS		1000	\$ 5,500.00
74	SAND DOWN, PATCH AND SPRAY PAINT ON FRONT BUMPER, DOOR, A PILLAR, B PILLAR, FRONT COVER, LH SIDE COVER AND INNER PART OF FRONT COVER			1000 \$ 3,500.00
75	To focus headlamps and check front wiring and lighting operation. LABOUR TO FIX ELECTRICAL CABLES UNDERNEATH DASHBOARD			250 \$ 800.00
76	To dismantle and reinstall 18ft Refrigerated Box and tailgate		1800	\$ 2,500.00
77	To realignment for cabin and chassis			\$ 2,800.00
78	To realignment for Tyers			800 \$ 300.00
TOTAL REPAIR COST FOR TRUCK (BEFORE GST)				\$ 55,193.00
Total Amount				\$ 125,593.00
7% gst				\$ 8,791.51
Bal amount due				\$ 134,384.51

Remark: LOSS OF USE 25 days x \$450

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/08/2022 16:34 (SGT)
Reported by Driver
Date of Accident 11/06/2022 06:10 (SGT)
Exact Location of Accident CTE, Singapore
Additional Location Information towards SLE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP1929J
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner Systematic Airconditioning Pte Ltd
Company Reg No 1XXXXX703G
Email Address shah@systematicaircon.com
Mobile Phone No (Phone) +65-87175009
Alternative Phone No (Office) +65-64847188

VEHICLE PARTICULARS

Manufacturer Isuzu
Model NQR75UL5A
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 5193

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd
Policy Number / Cover Note Number SD2206793/VZ/R02

DRIVER

Name of Driver Afendy Bin Abdul Jalil
NRIC No SXXXX155H
Date Of Birth 07/07/1981
Occupation Outdoor

Describe Circumstance of the Accident

ENCLOSED POLICE REPORT.

VEHICLE IS STILL AT POLICE COMPOUND.
DRIVER STILL ON MC/HOSPITAL.

OF SYSTEMATIC


I AM MR SEAH KENG LAM, OPERATIONS MGR,
REPORTING ON BEHALF OF DRIVER.

→ VEHICLE TOWED OUT TO OUR WORKSHOP
SYSTEMATIC AIRCONDITIONING ON 4.8.2022-P.

TP CLAM: SYSTEMATIC


Declaration

(We declare the foregoing particulars are true in every respect.)


Policyholder's Signature / Date & Time




Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

4/8@
