

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGS9990A

at Workshop m/s

Zoom

of

Insured:

SLU 5128E

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

55k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

765h

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 830732

Date / Time

Action / Instruction

Dep 10500

1/10/22 L/S 85800 informed El.1

Veh No:

SGS9990A

Yr Regn:

27/03/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

KIA Forte K3

c.c 1591

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

95169

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAFJ411MH 5714368

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

apollo

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

15/08/22

D.O.I.

17/8/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

not followed
17/8/22

22 August 2022

2/5 \$5800
6 days
the price after repair

REG NO.: SGS 9990 A
MAKE/MODEL: KIA CERATO K3

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
2	Front headlamps <i>n/s an o/s one</i>	\$ 653.50 1,307.00 <i>12C</i>
1	Front bumper <i>De/To n</i>	\$ 698 858.60 <i>/</i>
1	Front bumper inner sponge <i>To n</i>	\$ 123.60 <i>/</i>
1	Front bumper lower grille <i>scr/cr</i>	\$ 88.00 <i>/</i>
1	Front bumper reinforcement <i>Buf</i>	\$ 244.50 <i>/</i>
1	Front bumper logo <i>ner</i>	\$ 58 75.00 <i>/</i>
2	Front bumper side retainers <i>ner</i>	\$ 65.60 <i>/</i>
1	Front bumper top beam <i>nn</i>	\$ 204.00 <i>X</i>
1	Front number plate garnish <i>nn</i>	\$ 68.60 <i>X</i>
1	Rear boot lid <i>nn/Buf</i>	\$ 793.80 <i>/</i>
2	Rear boot hinges <i>nn</i>	\$ 250.00 <i>X</i>
1	Rear boot inner trim <i>nn</i>	\$ 130.00 <i>X</i>
2	Rear boot lamps <i>nn</i>	\$ 373.00 <i>X</i>
1	Rear boot inner lock <i>Buf</i>	\$ 126.50 <i>/</i>
1	Rear boot lock catch <i>nn</i>	\$ 48.00 <i>X</i>
1	Rear boot rubber <i>nn</i>	\$ 128.60 <i>X</i>
1	Rear boot "KIA" emblem <i>ner</i>	\$ 52.50 <i>/</i>
1	Rear boot "CERATO" emblem <i>ner</i>	\$ 42.50 <i>/</i>
1	Rear boot "K3" emblem <i>ner</i>	\$ 32.50 <i>/</i>
1	Rear boot "C&C" emblem <i>ner</i>	\$ 45.60 <i>/</i>
2	Rear taillamps <i>cr</i>	\$ 975.20 <i>/</i>
1	Rear end panel <i>n</i>	\$ 598.50 <i>X</i>
1	Rear end panel inner garnish <i>nn</i>	\$ 152.50 <i>X</i>
1	Rear smart keyless sensor <i>nn</i>	\$ 185.50 <i>X</i>
1	Rear bumper <i>DIS</i>	\$ 658.00 <i>/</i>
1	Rear bumper inner sponge <i>NZ</i>	\$ 145.50 <i>X</i>
2	Rear bumper reflectors <i>nn</i>	\$ 156.00 <i>X</i>
1	Rear bumper reinforcement <i>cr</i>	\$ 298 356.00 <i>/</i>
1 <i>1 set</i>	Rear bumper reverse sensor <i>shorted</i>	\$ 305.00 <i>2005/N</i>
3	Rear bumper reinforcement brackets <i>nn</i>	\$ 68.70 <i>X</i>
2	Rear bumper side retainers <i>ner</i>	\$ 77.00 <i>/</i>
1	Rear bumper lower diffuser <i>DIS</i>	\$ 298.50 <i>/</i>
1	Rear exhaust silencer <i>nn</i>	\$ 726.50 <i>X</i>
2	Rear exhaust mountings <i>nn</i>	\$ 87.00 <i>X</i>
		\$ 9,847.80
	Less 10%	\$ 984.78
		\$ 8,863.02

SPECIAL NETT ITEMS

1	Rear boot inner trim clip (1 set)	<i>new</i>	\$	50.00	✓
1	Rear bumper clip (1 set)	<i>new</i>	\$	50.00	✓
1	Front number plate	<i>SEA</i>	\$	50.00	40
			\$	150.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	} 30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	
3	To remove and refit inner garnishes.	\$	150.00	80
4	To remove and refit rear reverse sensor.	\$	150.00	50
5	To transfer boot lid mechanism and wiring assembly.	\$	80.00	60
6	To apply undercoating.	\$	200.00	30
7	Panel beating.	\$	1,600.00	800
8	To re-spray painting on the affected areas.	\$	1,500.00	1100
		\$	3,840.00	

GRAND TOTAL :

\$ 12,853.02

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-5331.30
102
4798.17
340
2150
7248.17
22
5830