



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 8202Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	399.60	399.60
10	FRONT BUMPER CLIPS @\$2.50	NECESSARY	25.00	25.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	332.30	-
1	FRONT BUMPER LOWER LIP (RIGHT)	DEFORMED	200.00	200.00
1	FRONT BUMPER SIDE RETAINER (RIGHT)	DISTORTED	65.90	65.90
1	FRONT BUMPER FOG LAMP COVER (RIGHT)	NOT NECESSARY	137.70	-
1	FRONT GRILLE	CUT	299.95	299.95
1	FRONT GRILLE TOYOTA LOGO	NECESSARY	37.80	37.80
1	FRONT RIGHT HAND HEAD LAMP	CRACKED	287.90	287.90
1	FRONT RIGHT HAND HEAD LAMP RIM	NOT NECESSARY	156.90	-
1	FRONT RIGHT HAND SIDE LAMP	CRACKED	128.60	128.60
1	FRONT RIGHT SIDE TYRE RIM	NOT NECESSARY	399.60	-
1	FRONT BONNET	BENT	519.80	519.80
2	FRONT BONNET HINGE @\$65.60	BENT	131.20	131.20
1	FRONT BONNET EMBLEM	NOT NECESSARY	55.60	-
1	FRONT RIGHT SIDE FENDER	BENT	549.90	549.90
1	FRONT RIGHT SIDE FENDER INNER COWLING	TORN	197.85	197.85
8	FRONT RIGHT SIDE FENDER INNER COWLING CLIPS @ \$2.50	NECESSARY	20.00	20.00
1	FRONT RIGHT SIDE FENDER SIGNAL LAMP	NOT NECESSARY	49.80	-
	LESS 25% DISCOUNT		-	-715.88
			3,995.40	2,147.62
	<u>LABOUR</u>			
	TO SPRAY ANTI-RUST COATING ON NEW & AFFECTED PANELS.		200.00	50.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA, CUTTING FRONT RIGHT SIDE FENDER, DISMANTLE AND REPLACE THE ABOVE MENTIONED PARTS.		1,200.00	700.00
	TO RESPRAY PAINTING ON FRONT BONNET, FRONT RIGHT SIDE FENDER, FRONT BUMPER & BUMPER LOWER LIP.		1,100.00	800.00

Report Ref No. CS/INC22007869/Tcy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK REAR LIGHTING AND ELECTRICAL WIRING SYSTEMS INCLUDE PERFORMING WATER LEAKAGE.		120.00	30.00
			2,620.00	1,580.00
GRAND TOTAL			6,615.40	3,727.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,000.00

Report Ref No. CS/INC22007869/Tcy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.