

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007878/AVY3Q2**Date:** 21/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00013422107
Claimant Vehicle No :	SJN1210L	Insured Vehicle No :	PC982K
Date of Loss:	11/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D205603/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN1210L	Engine No:	1NZX860818
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305098459
Reg. Date:	03/02/2009 (Man. Year: 2008)	Odometer:	195317 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,730.95	6,624.82	5,106.13	43.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,710.00	3,380.00	1,330.00	28.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,440.95	10,004.82	6,436.13	39.15
Approved Total (Overridden) (\$\$)		8,000.00		
Nett Amount (\$\$)	16,440.95	8,000.00	8,440.95	51.34

INSPECTION

Date of Assignment:	19/09/2022	BLK 1 KAKI BUKIT AVE 6 #01-08 AUTOBAY @KAKI BUKIT Singapore 417883 Repairer: Tsl Auto Garage (HQ)
Date Inspected:	16/08/2022 Inspected At:	
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN1210L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Distorted	589.30 FL	*589.30 FL
2	2		*REAR BUMPER BRACKET	Dented	89.80 FL	*89.80 FL
3	2		*REAR BUMPER SIDE RETAINER	Damaged	88.80 FL	*88.80 FL
4	2		*REAR BUMPER LOWER REFLECTOR	Cracked	128.60 FL	*128.60 FL
5	1		*REAR BOOTLID ASSY	Distorted	771.40 FL	*771.40 FL
6	1		*REAR BOOTLID WEATHERSTRIP	Cut	168.70 FL	*168.70 FL
7	1		*REAR BOOTLID LOCK	Jammed	165.90 FL	*165.90 FL
8	1		*REAR BOOTLID LOCK CYLINDER	Jammed	195.10 FL	*195.10 FL
9	1		*REAR BOOTLID LOCK CATCH	Bent	62.40 FL	*62.40 FL
10	1		*REAR BOOTLID OUTER GARNISH	Cracked	172.80 FL	*172.80 FL
11	2		*REAR BOOTLID NUMBER PLATE LAMPS	Not Necessary	120.10 FL	*- FL
12	1		*REAR BOOTLID CENTRE LOGO	Necessary	68.30 FL	*68.30 FL
13	1		*REAR BOOTLID E EMBLEM	Necessary	64.30 FL	*64.30 FL
14	1		*REAR BOOTLID VIOS EMBLEM	Necessary	68.80 FL	*68.80 FL
15	1		*SET REAR BOOTLID RUBBER STOPPER	Necessary	48.60 FL	*48.60 FL
16	2		*REAR BOOTLID HINGES	Bent	145.50 FL	*145.50 FL
17	1		*REAR RIGHT FENDER	Repair	992.40 FL	*- FL
18	1		*REAR LEFT FENDER	Buckled	992.40 FL	*992.40 FL
19	1		*REAR LEFT FENDER INNER SIDE GARNISH	Torn	379.40 FL	*285.00 FL
20	1		*REAR RIGHT FENDER INNER SIDE GARNISH	Torn	379.40 FL	*285.00 FL
21	1		*REAR LEFT FENDER INNER COWLING	Not Necessary	146.20 FL	*- FL
22	1		*REAR RIGHT FENDER INNER COWLING	Not Necessary	146.20 FL	*- FL
23	1		*REAR LEFT TAILLAMP	Cracked	457.80 FL	*345.00 FL
24	1		*REAR RIGHT TAILLAMP	Cracked	457.80 FL	*345.00 FL
25	1		*REAR LEFT TAILLAMP LOWER BRACKET	Damaged	26.30 FL	*26.30 FL
26	1		*REAR RIGHT TAILLAMP LOWER BRACKET	Damaged	26.30 FL	*26.30 FL
27	1		*REAR END PANEL	Distorted	864.80 FL	*660.00 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	96.20 FL	*96.20 FL
29	1		*REAR FLOOR PANEL	Repair	972.10 FL	*- FL
30	1		*SPARE TYRE TOP CARPET	Not Necessary	228.50 FL	*- FL
31	2		*SPARE TYRE TOP SIDE SPONGE	Deformed	220.80 FL	*220.80 FL
32	1		*SPARE TYRE TOP BOARD	Torn	152.70 FL	*152.70 FL
33	1		*REAR EXHAUST MUFFLER ASSY	Repair	987.90 FL	*- FL
34	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	66.10 FL	*- FL
35	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	166.10 FL	*166.10 FL
36	10		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
37	4		*REAR END PANEL TOP GARNISH	Necessary	30.00 FS	*10.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	140.00 FS	*60.00 FS
39	2		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
40	1		*REAR LEFT FENDER SEALANT	Necessary	100.00 FS	*60.00 FS
41	1		*REAR RIGHT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
42	4		*REAR LEFT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
43	4		*REAR RIGHT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
44	6		*REAR LEFT FENDER INNER SIDE GARNISH CLIPS	Necessary	40.00 FS	*30.00 FS
45	6		*REAR RIGHT FENDER INNER SIDE GARNISH CLIPS	Necessary	40.00 FS	*30.00 FS
46	1		*REAR NO PLATE	Bent	100.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

9/21/22, 12:04 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	4		*REAR BOOTLID OUTER GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
48	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*60.00 FS
49	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
50	1		*REAR FLOOR PANEL INSULATOR PAD	Not Necessary	180.00 FS	*- FS
51	1		*REAR WINDSCREEN GLASS ASSY	Cut	1,410.10 FL	*980.00 FL
52	1		*REAR WINDSCREEN GLASS MOULDING	Repeated	166.10 FL	*- FL
53	1		*REAR LEFT TAILLAMP LOWER PANEL	Dented	485.30 FL	*252.00 FL
54	1		*REAR RIGHT TAILLAMP LOWER PANEL	Dented	485.30 FL	*252.00 FL
55	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
56	1		*REAR WINDSCREEN GLASS SEAL	Necessary	100.00 FS	*40.00 FS
57	1		*REAR LEFT TAILLAMP LOWER PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
58	1		*REAR RIGHT TAILLAMP LOWER PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,044.60	8,603.10
- List Item Discount on L Items 25.00/25.00% (S\$)					3,313.65	1,978.28
Total Parts (S\$)					11,730.95	6,624.82
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS INCLUDING FLOOR PANEL	New	1,400.00	1,300.00
2	TO PUTTY AN SPRAY PAINTING REAR PORTION	New	1,400.00	1,300.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	80.00
6	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	80.00
7	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	180.00	80.00
8	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	100.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
11	TOWING ACCIDENT VEHICLE TO WORKSHOP	New	100.00	60.00
12	TO REPAIR STRAIGHTEN AND ALIGN BOTH REAR DOOR PANEL ASSY	New	350.00	0.00
13	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
14	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
Gross Labour Cost (S\$)			4,710.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >