Adjuster Report 3/15/23, 8:54 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd

11 Keppel Road, #11-01 ABI Plaza

Singapore 089057

Date:

Our File No:

CS/HLA22007881/KQY3E2

15/03/2023

B4154T52283474

49286 km

YV1FS28L0J2456855

REFERENCE

Date of Loss:

Insured/Claimant:

NG IMM 08/08/2022 Policy No:

Nature of Claim:

MP315524 OD

Claim No:

MPC03596/WF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

SJJ2606T

Make & Model: Reg. Date:

VOLVO S60, 1.5 T2 (A) 28/12/2017 (Man. Year: 2017)

Metallic Blue

Engine Capacity:

1498 cc Market Value/New Car Price: S\$81,000.00

Sum Insured (S\$):

Market Value/New Car Price

Yes

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Front Right Side:

Steering (Serviceable):

Engine Modification:

Yes No

Engine No:

Chassis No:

Odometer:

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/55 R16 Michelin 8 mm Michelin 8 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/55 R16 Michelin 8 mm

Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,655.00	6,160.00	495.00	7.44
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,010.00	1,420.00	590.00	29.35
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,665.00	7,580.00	1,085.00	12.52
	- Excess (S\$)	0.00	775.00	-775.00	
	(S\$)	8,665.00	6,805.00	1,860.00	21.47
	+ GST 7.00/7.00% (S\$)	606.55	476.35	130.20	21.47
	Nett Amount (S\$)	9,271.55	7,281.35	1,990.20	21.47

INSPECTION

Date of Assignment: 17/08/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell) ComfortDelGro Engineering Pte Ltd (Braddell)

Date Inspected:

18/08/2022 Inspected At:

205 Braddell Road

Singapore 579701

Estimated Period of Repair: 5.0 days

KENNETH KONG Adjuster:

SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: 143 VOLVO S60 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJJ2606T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR WING MIRROR ASSEMBLY	Broken	950.00 F	*950.00 F
2	1		*FRT RH DOOR WING MIRROR	Distorted	340.00 F	*340.00 F
3	1		*FRT RH DOOR (WCP)	Warped	2,850.00 F	*2,850.00 F
4	1		*FRT RH DOOR GLASS (WCP)	Cut	630.00 F	*630.00 F
5	1		*FRT RH DOOR FRAME MOULDING CHROME	Serviceable	450.00 F	*- F
6	1		*FRT RH DOOR GLASS MOULDING (WCP)	Dented	330.00 F	*330.00 F
7	1		*RH ROCKER PANEL GARNISH	Deep Cut	330.00 F	*330.00 F
8	1		*FRT RH FENDER (REPAIR) (NPA)	Repair	0.00 F	*- F
9	1		*FRT RH WHEEL RIM (REPAIR) (NPA)	Repair	0.00 F	*- F
10	1		*REAR RH DOOR (REPAIR) (NPA)	Repair	0.00 F	*- F
11	1		*REAR RH FENDER (REPAIR) (NPA)	Repair	0.00 F	*- F
12	1		*REAR RH WHEEL RIM (REPAIR) (NPA)	Repair	0.00 F	*- F
<u>Sup</u>	<u>pleme</u>	entary #1				
13	1		*FRONT RH DOOR WING MIRROR COVER (WCP)	Missing	170.00 F	*170.00 F
F=Fra	nchise	part.		_		
			+ Margin on L,	Sub Total (S\$) N Items 10.00/10.00% (S\$)	6,050.00 605.00	5,600.00 560.00
				Total Parts (S\$)	6,655.00	6,160.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT RIGHT DAMAGE PARTS	New	600.00	400.00
2	TO PUTTY & RESPRAY ON RGHT SIDE AFFECTED AREA	New	1,000.00	800.00
3	TO REPAIR & RESPRAY FRT RIGHT WHEEL RIM, REAR RIGHT WHEEL RIM	New	200.00	80.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO DO WHEEL ALIGNMENT	New	80.00	60.00
6	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD	New	80.00	60.00
	Gross Labour	Cost (S\$)	2,010.00	1,420.00
	Report was unsubmitted during this pri	nt-out.		_

< END OF ESTIMATES >