



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2674G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,785.50	-
1	BUMPER BRKT LH (CONSISTENT)	TO REPAIR SEE LABOUR	298.50	-
1	BUMPER CORNER LH ,END PIECES (CONSISTENT)	NOT NECESSARY	185.00	-
1	HEADLAMP LH (CONSISTENT)	NOT NECESSARY	1,546.50	-
1	HEADLAMP GARNISH (CONSISTENT)	CUT	458.90	458.90
1	SIGNAL LH (CONSISTENT)	BROKEN	295.50	295.50
1	STEP LOWER LH (CONSISTENT)	CUT	346.50	346.50
1	STEP UPPER LH (CONSISTENT)	CUT	346.50	346.50
1	STEP GARNISH (CONSISTENT)	CUT	288.50	288.50
1	STEP GARNISH UPPER (CONSISTENT)	CUT	450.80	450.80
	LESS 10% DISCOUNT		-600.22	-218.67
			5,401.98	1,968.03
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER LH AND LH DAMAGES PARTS.INCLUSIVE OF THE REPAIR OF BUMPER LH AND BUMPER BRKT LH.		850.00	400.00
	TO SPRAY PAINT ON AFFECTED AREAS .		450.00	200.00
	TO APPLY ANTIRUST ON AFFECTED AREAS .		80.00	30.00
	TO ADJUST FOCUS HEADLAMP.		80.00	30.00
			1,460.00	660.00
	GRAND TOTAL		6,861.98	2,628.03
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CC4/ASM22007882/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.