

VEHICLE SURVEY REPORTS																																				
<p>Chia Cheng Ee C/O Wah Yu Automotive Body Work 176 Sin Ming Drive Sin Ming AutoCare #05-09 Singapore 575721</p>																																				
1	<b>Reference</b> Job Reference No : 21/002359 Claim No : - Claim Type : Third Party Accident Date : 11/09/2021 Survey Date : 13/09/2021 Survey Report Date : 23/09/2021																																			
2	<b>Particulars Of Vehicle</b> Vehicle Registration No : SKD3666H Make & Model : Mazda 3 4-Door Sedan 1.5L Vehicle Registration Date : 24/09/2014 Chassis No : JM6BM42A8F0144666 Engine No : Blocked Colour : Red																																			
3	<b>Condition Of Vehicle And Tyres</b> <table border="0" style="width: 100%;"> <tr> <td><u>Mileage (KM)</u></td> <td><u>Brakes</u></td> <td><u>Steering</u></td> <td><u>Modification</u></td> </tr> <tr> <td>81785</td> <td>Serviceable</td> <td>Serviceable</td> <td>None</td> </tr> <tr> <td colspan="4"> </td> </tr> <tr> <td><u>Tyres</u></td> <td><u>Make</u></td> <td><u>Size</u></td> <td><u>Balance (MM)</u></td> </tr> <tr> <td>Front RHS</td> <td>Yokohama</td> <td>205/60R16</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Yokohama</td> <td>205/60R16</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Yokohama</td> <td>205/60R16</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Yokohama</td> <td>205/60R16</td> <td>6</td> </tr> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	81785	Serviceable	Serviceable	None					<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Yokohama	205/60R16	5	Front LHS	Yokohama	205/60R16	5	Rear RHS	Yokohama	205/60R16	6	Rear LHS	Yokohama	205/60R16	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																																	
81785	Serviceable	Serviceable	None																																	
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																																	
Front RHS	Yokohama	205/60R16	5																																	
Front LHS	Yokohama	205/60R16	5																																	
Rear RHS	Yokohama	205/60R16	6																																	
Rear LHS	Yokohama	205/60R16	6																																	
4	<b>Description Of Damages</b> The vehicle sustained damages at front left hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																																			
5	<b>Instruction</b> This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																																			

# AUTO PERFORMANCE APPRAISAL

Annex A

## Vehicle Assessment Reports

Ref No : 21/002359

### Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
<u>List Items</u>					
1	1	Front bumper	Deformed/broken	1,083.00	971.40 ✓ 1,083.00
2	1	Front bumper LH signal lamp cover	LH cut/RH reuse	90.00	✓ 45.00 HS HP
3	1	Front bumper LH signal lamp	Broken/smashed	164.00	164.00 ✓
4	1	Front bumper LH fog lamp cover	Broken/cut	48.80	48.80 ✓
5	1	Front bumper LH fog lamp	Grazed/cut	111.50	111.50 ✓
6	1	Front bumper LH fog lamp bracket	Broken/bent	18.20	18.20 ✓
7	2	Front bumper lower grille side cover	LH broken/RH reuse	58.80 of SVC	29.40 HS NH
8	2	Front bumper side retainer	LH broken/RH reuse	64.80 of SVC	32.40 ✓
9	1	Front bumper inner reinforcement outer cover	Serviceable/reuse	165.00	- SVC
10	1	Front bumper inner reinforcement	Dented/bent	593.00	593.00 SVC
11	1 set	Front bumper clips	Broken/necessary	40.00	40.00 ✓
12	1	LH Headlamp (HID)	Broken/smashed	2,357.30	2,357.30 ✓
13	1	LH headlamp washer nozzle	Bent/broken	254.60	254.60 NH
14	1	LH headlamp washer nozzle cover	Broken	89.60	89.60 ✓
15	1	Front grille	Deformed/broken	126.00	126.00 ✓
16	1	Front grille centre "MAZDA" logo	Necessary	36.00	36.00 ✓
17	1	Front grille LH chrome moulding	Bent/dented	185.60	185.60 ✓
18	1	Front grille LH inner bracket	Broken	106.00	106.00 HS NH
19	1	Front grille top cover	Deformed/broken	264.80	264.80 HS NH ✓
20	1	Front bonnet	Dented/bent	1,120.00	1,120.00 R
21	1	Front bonnet under rubber seal	Deformed/cut	86.00	86.00 NH
22	1	Front support panel	Broken	426.30	426.30 SVC
23	1	Front LH fender	Badly dented/bent	350.60	350.60 R
				7,839.90	7,568.10
				1,567.98	1,513.62
				Total : 6,271.92	6,054.48
<u>Special Nett Items</u>					
24	1	Front number plate	Serviceable/reuse	60.00	- NH
25	1L	Radiator coolant	Necessary	30.00	30.00 SVC
				Total : 90.00	30.00
				Total Spare Parts : 6,361.92	6,084.48

4490.60

Less discount 20%

3592.48

# AUTO PERFORMANCE APPRAISAL

## Vehicle Assessment Reports

Annex B

Ref No : 21/002359

### Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,000.00	<del>700.00</del> 600 - 700 -
2	To putty and respray painting on affected areas.	1,200.00	<del>900.00</del> 600 - 700 -
3	To remove, refix aircon condenser, pipes, drier vacuum and recharge gas.	140.00	120.00 40
4	To check wirings and lightings.	50.00	<del>30.00</del> 30 -
5	To supplied and applied anti rust treatments.	100.00	<del>60.00</del> 40 -
Total Labour :		2,490.00	1,810.00
Total Spare Parts :		6,361.92	6,084.48
Total Labour :		2,490.00	1,810.00
Total Repair Costs :		8,851.92	7,894.48

### Assessor's Recommendation

Repairer Estimate : 8,851.92  
Our Adjustment : 7,894.48

### Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$6,300.00, with a repair period of 6 working days.

Surveyed By:

Lek Boon Hwee  
Automobile Appraiser

5062.48  
4/5 4,000/-  
4  
\$ days.