



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 4786H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	50.00
1	LAMP ASSY ,DAYTIME (SN)	NOT NECESSARY	632.20	-
1	EXTENSION,FR (SN)	NECESSARY	36.90	36.90
1	COVER ,FR BUMPER (SN)	DEFORMED	602.60	602.60
1	SUPPORT ,FR BUMPER (SN)	NOT NECESSARY	73.70	-
1	EMBLEM ,SIDE PANEL (SN)	NECESSARY	59.20	59.20
1	COVER ,OUTER MIRROR (SN)	TO REPAIR SEE LABOUR	142.30	-
1	MIRROR ASSY ,OUTER (SN)	NOT NECESSARY	1,399.60	-
1	CAP SUB-ASSY ,WHEEL (SN)	NOT NECESSARY	254.90	-
			3,251.40	748.70
	<u>LABOUR</u>			
	TO RESET ECU AND REPROGRAMME .	NOT NECESSARY	180.00	-
	TO CHECK WIRING AND LIGHTING.TO FOCUS HEADLAMP.		122.40	122.40
	TO REPLACE/REPAIR FRONT LH ACCIDENT DAMAGE PARTS .STRAIGHTEN /REALIGN ALL OTHER AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF COVER ,OUTER MIRROR .		2,160.00	720.00
	TO SPRAY PAINT ON FRONT LH SIDE ACCIDENT AFFECTED AREAS .		2,360.00	1,380.00
			4,822.40	2,222.40
	GRAND TOTAL		8,073.80	2,971.10
	RECOMMENDED COST OF REPAIRS			2,971.10

Report Ref No. CS/FCI22007891/Tqy3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.