ASSIG	PAGO3/TVYS
From:	Carrier II Jorg Aug
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TE/ VS / TP RES / OD RES / EVA / INV / MV	Truck / Traller or
T- lean a-1/-1:1-11	Make: Toyota Migre. c.c 2982.
	Colour White A/C: Insured / Std / NI / NA
of	Sp.Reading 78 278 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JTFHT02P600250242
Claims Nu	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insued: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inproder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / S/Rim / STD A/Rim or
· · ·	Tyre Size: F:
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YORO or
Bal. or Market Value:	Front Rear
IDAC Accident Roort Consistent? : Yes or No	R/Bal, C mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. /9/8/27
Lum Sum: % 3 Val.: Yes or No	Survey held at Phonih
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
)	
	1
Date/Time, File Pass 10? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add F	ee:; Site insp (\$) _s+Rssi
•	: Interview (\$) Photos
Repet Formal :	: Tech. Invs (\$) Others

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS Vehicle No: GBK4930H Report No : SA1X228H0003 Chassis No: JTFHT02P600250242 Engine No: 1KDB026284 Date : 19/8/2022 MAKE: TOYOTA **MODEL: HIACE VAN TURBO 5DR MT TYPE** : COMMERCIAL Replacement of Damaged Parts S/No. Description Qty Our Recommendation 1 Tailgate 1 \$2,293.20 2 Tailgate emblem 1 \$72.20 3 Rear bumper 1 \$481.80 4 Taillamp lower garnish LH 1 \$99.80 /02 5 Taillamp LH 1 \$324.70 CMg \$3,271.70 Less 25% \$817.93 Total (P) \$2,453.78 S/N 1 Sticker 70km/h \$10.00 2 Sticker Hiace \$79.50 1 3 Rear windscreen sealant 1 \$50.00 4 Reverse sensor [1 set to Consultants hence notify \$250.00 200 nw. Total (S/N) \$389.50 the Repairer of the following: To resurvey before/after spray painting • To display damaged part(s) during resurvey Total (Parts & S/N): \$2,843.28 · Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" trasis **Labour Charges** No illegal inodification(s) is allowed · Supplementary item(s) must be resurveyed and To check wiring subject to final approval from Insurance Company \$30.00 Acknowledged by Repairer To remove and transfer/reinstate the rear windscreen \$150.00 X Date: To dismantle and renew/refit/transfer the tail gate fittings, \$100.00 🛭 hydraulic dampers, wiper motor, lock regulator gear to the To dismantle and renew the reverse sensor including re-\$60.00 30 set of same. To dismantle and replace of the accident damaged parts; to heat/weld, cut-off the inner/outer panel, tailgate, \$600.00 400 tailgate lock, rear bumper, floor panel including knocking, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, rear bumper, tail lamp lower garnish RH, inner/outer \$800.00 500 panel, including knocking, repair, reshape and adjust of same. To apply rustproofing on the repaired and replaced \$60.00 30 tailgate and fender RH. **Total Labour:** \$1,800.00 Final Repair Cost to Vehicle No: GBK4930H \$4,643.28 **Amount** Lump Sum Discount -20% \$928.66

n

Cl

ı

Total

Add GST 7%

Grand Total

Tanfikh 97495749/6256356/
1918/778 10304h \$4,643.2
1/5 Resumm after ce part \$3,714.6
fanflin & lithardour \$260.0
\$3,974.6 \$3,714.62 \$260.02 \$3,974.64