



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 4930H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	TO REPAIR SEE LABOUR	2,293.20	-
1	TAILGATE EMBLEM	NECESSARY	72.20	72.20
1	REAR BUMPER	TO REPAIR SEE LABOUR	481.80	-
1	TAILLAMP LOWER GARNISH LH	TO REPAIR SEE LABOUR	99.80	-
1	TAILLAMP LH	CRACKED	324.70	324.70
	LESS 25% DISCOUNT		-817.93	-99.23
			2,453.77	297.67
<b><u>SPECIAL NETT ITEMS</u></b>				
1	STICKER 70KM/H (SN)	NECESSARY	10.00	10.00
1	STICKER HIACE (SN)	NECESSARY	79.50	79.50
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
			389.50	289.50
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		30.00	30.00
	TO REMOVE AND TRANSFER/REINSTATE THE REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE AND RENEW/REFIT/TRANSFER THE TAIL GATE FITTINGS, HYDRAULIC DAMPERS, WIPER MOTOR, LOCK REGULATOR GEAR TO THE.	NOT NECESSARY	100.00	-
	TO DISMANTLE AND RENEW THE REVERSE SENSOR INCLUDING RE-SET OF SAME.		60.00	30.00
	TO DISMANTLE AND REPLACE OF THE ACCIDENT DAMAGED PARTS; TO HEAT/WELD, CUT-OFF THE INNER/OUTER PANEL, TAILGATE, TAILGATE LOCK, REAR BUMPER, FLOOR PANEL INCLUDING KNOCKING, REPAIR, RESHAPE AND ADJUST OF SAME. INCLUSIVE OF THE REPAIR OF TAILGATE, REAR BUMPER & TAILLAMP LOWER GARNISH LH.		600.00	400.00
	TO PUTTY AND SPRAY PAINTING ON TAIL GATE INNER AND OUTER, REAR BUMPER, TAIL LAMP LOWER GARNISH RH, INNER/OUTER PANEL, INCLUDING KNOCKING, REPAIR, RESHAPE AND ADJUST OF SAME.		800.00	500.00

Report Ref No. CS/FCI22007903/Tvy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED TAILGATE AND FENDER RH.		60.00	30.00
			1,800.00	990.00
GRAND TOTAL			4,643.27	1,577.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/FCI22007903/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.