



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22007903/Tvy3m4	
			Date: 13/09/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 3358A	Veh. Inspected	GBK 4930H	
Policy No.	D-22099187MFBP	Coverage (\$)	0.00	
Claim No.	D22002567MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	18/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTFHT02P600250242	Colour	WHITE	
Odometer	78278 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2022	Inspection Date	19/08/2022	
Survey held at	ABWIN LEASING PTE LTD 25 SENANG CRESCENT, SINGAPORE 416598			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	