



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 7259J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BUCKLED / MTG CRACKED	1,380.00	1,220.00
1	FRONT BUMPER SIDE RETAINER LHS	SERVICEABLE	60.00	-
1	FRONT BUMPER SIDE RETAINER RHS	SERVICEABLE	60.00	-
1	FRONT REINFORCEMENT PANEL	BENT	550.00	420.00
1	FRONT BUMPER TOWING CAP	SERVICEABLE	50.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	500.00	-
1	FRONT GRILLE	SERVICEABLE	690.00	-
1	FRONT GRILLE EMBLEM "H"	SERVICEABLE	80.00	-
1	FRONT FOGLAMP COVER LHS	SERVICEABLE	80.00	-
1	FRONT FOGLAMP COVER RHS	SERVICEABLE	80.00	-
1	FRONT HEADLAMP LHS	SERVICEABLE	1,350.00	-
1	FRONT HEADLAMP LOWER BRACKET LHS	SERVICEABLE	50.00	-
1	FRONT HEADLAMP RHS	SERVICEABLE	1,350.00	-
1	FRONT HEADLAMP LOWER BRACKET RHS	SERVICEABLE	50.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	690.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	200.00	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	150.00	-
	LESS 20% DISCOUNT		-1,474.00	-328.00
			5,896.00	1,312.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	SET FRONT SENSOR (SN)	SERVICEABLE	250.00	-
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	100.00	-
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
			470.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL AND FRONT BRACE PANEL.		1,400.00	200.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,400.00	360.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		100.00	15.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO REMOVE AND RE-FIX FRONT AIRCOND CONDENSER AND RE-FILL GAS.	NOT NECESSARY	200.00	-
	TO REMOVE AND RE-FIX FRONT SENSOR ASSY.		100.00	50.00
	TO REMOVE AND RE-FIX FRONT RADIATOR AND RE-FILL COOLANT.	NOT NECESSARY	150.00	-
			3,450.00	625.00
GRAND TOTAL			9,816.00	1,997.00
RECOMMENDED COST OF REPAIRS				1,997.00

Report Ref No. CS/FCI22007912/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.