



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22007912/Kvy3e2 Date: 05/05/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SG 1844M	Veh. Inspected	SMZ 7259J
Policy No.		Coverage (\$)	0.00
Claim No.	D22002577MFBP	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	18/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GR11030932	Colour	METALLIC BLUE
Odometer	26776 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	DUNLOP	7 mm
L/H Front Tyre	185/60 R15	DUNLOP	7 mm
R/H Rear Tyre	185/60 R15	DUNLOP	7 mm
L/H Rear Tyre	185/60 R15	DUNLOP	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	24/07/2022	Inspection Date	18/10/2022
Survey held at	160 SIN MING DRIVE AUTOCITY #02-04		
Repairer	CAR TIMES AUTOLUTION PTE LTD		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	