

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007915/KVY3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00242062100

Claimant Vehicle No : SFR788U **Insured Vehicle No :** SNC1261A

Date of Loss: 17/08/2022 Nature of Claim: TP Claim No: SNM22D205802/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFR788U**

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3226086

Reg. Date: 03/03/2009 (Man. Year: 2009) Chassis No: JTDER12W003001781

Colour: Metallic Dark Blue Odometer: 257472 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 7 mm Rear Left Side: Bridgestone 8 mm

Front Right Side: Dunlop 7 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,425.75	2,472.07	1,953.68	44.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,910.00	1,500.00	1,410.00	48.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,335.75	3,972.07	3,363.68	45.85
Approved Total (Overridden) (S\$)		3,150.00		
Nett Amount (S\$)	7,335.75	3,150.00	4,185.75	57.06

INSPECTION

Date of Assignment: 23/08/2022

Date Inspected: 22/08/2022 Inspected At: Tropical Tech Automobile Services (HQ)
BLK 5032 ANG MO KIO AVENUE 3, #01-303
INDUSTRIAL PARK 2
Singapore 569535

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2022)	
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SFR788U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Serviceable	1,149.00 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	207.00 FL	*207.00 FL
3	1		*REAR BOOT	Bent	1,348.00 FL	*1,329.00 FL
4	1		*REAR BOOT LICENSE LAMP OUTER CHROME MOULDING	Serviceable	230.00 FL	*- FL
5	1		*REAR LH TAIL LAMP	Mtg Cracked	655.00 FL	*565.10 FL
6	1		*REAR END PANEL	Bent	1,034.00 FL	*484.00 FL
7	1		*REAR BUMPER	Cracked / Buckled	690.00 FL	*590.00 FL
8	1		*REAR BUMPER REFLECTOR (LH)	Serviceable	87.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER (LH)	Distorted	121.00 FL	*121.00 FL
10	1		*REAR LICENSE SMART PLATE & CASING	Serviceable	35.00 FS	*- FS
11	1		*REAR BUMPER PARKING SENSOR KIT	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,806.00	3,296.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,380.25	824.03
Total Parts (\$\$)	4,425.75	2,472.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT REAR WINDSCREEN	New	250.00	120.00
2	HEAT/WELD/CUT /RENEW REAR END PANEL ,HEAT /WELD /BEATING REAR LH FENDER ,HEAT /WELD/BEATING /PULL /STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	800.00	600.00
3	REMOVE AND TRANSFER REAR BOOT NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
4	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
5	REMOVE AND REFIT REAR BOOT ,REAR BOOT LICENSE LAMP OUTER CHROME MOULDING,REAR LH TAIL LAMP,REAR BUMPER ,REAR BUMPER REFLECTOR (LH) ,REAR BUMPER SIDE RETAINER (LH) }	New	0.00	0.00
6	TO CHECK & REFIT REAR TAIL LAMP WIRING HARNESS	New	60.00	20.00
7	UNDER COATING ON VEHICLE REAR PORTION	New	200.00	60.00
8	PUTTY /PRIMER APPLICATION ,SPRAY PAINTING REAR BOOT ,REAR LH FENDER ,REAR END PANEL ,REAR BUMPER	New	1,600.00	700.00
Gross Labour Cost (\$\$)			2,910.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >