

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	SOMPO INSURAN	R	ef:	CS3/SMO22007917/TEcy3m4	
	50 RAFFLES PLAC SINGAPORE LAND	Da	ate:	11/10/2022	
			Co	ode:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBH 4978L	Veh. Inspected		SLV 7564K
	Policy No.		Coverage (\$)		0.00
	Claim No.	CMTD2202833/AGC	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		18/08/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CITY	c.c		1497
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	MRHGM6660JT000297	Colour		BLUE
	Odometer	66912 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	185/55 R16	BRIDGESTONE		6 mm
	L/H Front Tyre	185/55 R16	BRIDGESTONE		6 mm
	R/H Rear Tyre	185/55 R16	BRIDGESTONE		6 mm
	L/H Rear Tyre	185/55 R16	BRIDGESTONE		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION & UNDERCARRIAGE.				
5. General Information					
	Accident Date	12/08/2022	Inspect Date / Tin	ne	22/08/2022 (03:57 PM)
	Survey held at	PROWERKZ GARAGE PTE LTD)		
		25 KAKI BUKIT RD 4 #06-87 SYNERGY @ KB SINGAPORE 417800			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

Report Ref No. CS3/SMO22007917/TEcy3m4

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser