



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 8855A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR N/S DOOR	TO REPAIR SEE LABOUR	1,138.00	-
1	REAR N/S DOOR FRAME BLACK STICKER	NOT NECESSARY	27.00	-
18	REAR N/S DOOR INNER TRIM BOARD CLIPS @\$6.00	NOT NECESSARY	108.00	-
1	N/S ROCKER PANEL SIDESKIRT	CRACKED	685.00	685.00
10	N/S ROCKER PANEL SIDESKIRT CLIPS @\$6.50	NECESSARY	65.00	65.00
1	REAR N/S SPORT RIM	TO REPAIR SEE LABOUR	585.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	688.00	-
1	REAR BUMPER N/S SIDE RETAINER	NOT NECESSARY	28.00	-
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
6	REAR N/S FENDER INNER GARNISH CLIPS @\$6.50	NOT NECESSARY	39.00	-
	LESS 20% DISCOUNT		-679.60	-157.00
			2,718.40	628.00
	<u>LABOUR</u>			
	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM.		50.00	20.00
	TO REMOVE & REFIX REAR N/S DOOR INNER TRIM BOARD COVER ,GLASS ,INNER LOCK ,GLASS REGULATOR ,CHANNEL,WEATHERSTRIP MOULDING ,HANDLE & NECESSARY PARTS.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIX CUSHION SEAT ,CARPET ,FLOOR MAT,GARNISH & NECESSARY PARTS ,TO ENABLE REPAIR REAR N/S FENDER & NECESSARY PARTS.	NOT NECESSARY	120.00	-
	TO CHECK & ADJUST WHEEL ALIGNMENT & BALANCING.		120.00	60.00
	TO REMOVE,REFIX & PUMP SEALANT FOR ROCKER PANEL SIDESKIRT.		120.00	60.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	NOT NECESSARY	90.00	-
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR N/S FENDER & NECESSARY PARTS,TO WELD ,RENEW & ALIGN ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR N/S DOOR ,REAR N/S SPORT RIM AND REAR BUMPER.		950.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		1,250.00	1,150.00
			2,850.00	1,890.00
GRAND TOTAL			5,568.40	2,518.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/AGI22007920/Uny3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.