

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22007929/APA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001027561
Claimant Vehicle No :	SNF6793H	Insured Vehicle No :	YP7322U
Date of Loss:	11/08/2022	Nature of Claim:	TP
		Claim No:	202222006184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF6793H		
Make & Model:	MAZDA 3, 1.5 5DR M-HYBRID ASTINA I2 (A)	Engine No:	P520816236
Reg. Date:	15/06/2022 (Man. Year: 2022)	Chassis No:	JM6BP2SAAN1150882
Colour:	White	Odometer:	4850 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R18	Rear Tyre Size:	215/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,398.84	2,230.48	20,168.36	90.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,518.00	1,180.00	3,338.00	73.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,916.84	3,410.48	23,506.36	87.33
Approved Total (Overridden) (S\$)		2,450.00		
Nett Amount (S\$)	26,916.84	2,450.00	24,466.84	90.90
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		3,088.45		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment:	18/08/2022	
Date Inspected:	08/09/2022	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2023)
Parts:	143	MAZDA 3 1.5 5DR M-HYBRID ASTINA I2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF6793H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	987.90 FL	*867.30 FL
2	1		*FRT BUMPER AIR GUIDE RH (BRAKE)	Not Necessary	95.60 FL	*- FL
3	1		*FRT BUMPER AIR GUIDE LH (BRAKE)	Not Necessary	95.60 FL	*- FL
4	1		*PLATE SEAL RH FRT BUMPER	Necessary	49.00 FL	*49.00 FL
5	1		*PLATE SEAL LH FRT BUMPER	Necessary	49.00 FL	*49.00 FL
6	1		*FRT BUMPER SIDE RETAINER RH	Not Necessary	78.50 FL	*- FL
7	1		*FRT BUMPER SIDE RETAINER LH	Not Necessary	78.50 FL	*- FL
8	1		*FRT FOGLAMP COVER RH	Not Necessary	87.50 FL	*- FL
9	1		*FRT FOGLAMP COVER LH	Not Necessary	87.50 FL	*- FL
10	1		*FRT BUMPER SIDE RETAINER SMALL RH	Necessary	85.60 FL	*85.60 FL
11	1		*FRT BUMPER SIDE RETAINER SMALL LH	Necessary	85.60 FL	*85.60 FL
12	1		*FRT BUMPER REINFORCEMENT LOW	Not Necessary	198.50 FL	*- FL
13	1		*FRT NUMBER PLATE BASE	Not Necessary	128.50 FL	*- FL
14	1		*FRT RADAR SENSOR	Not Necessary	3,303.50 FL	*- FL
15	1		*FRT BUMPER PARKING SENSOR WIRE HA	Not Necessary	746.00 FL	*- FL
16	2		*FRT BUMPER PARKING SENSOR HOLDER	Not Necessary	116.00 FL	*- FL
17	2		*FRT BUMPER PARKING SENSOR	Not Necessary	456.00 FL	*- FL
18	1		*FRT BUMPER TOW COVER	Not Necessary	68.00 FL	*- FL
19	1		*FRT BUMPER PLATE SET CENTER	Not Necessary	58.90 FL	*- FL
20	1		*FRT BUMPER CENTRE GARNISH	Not Necessary	63.00 FL	*- FL
21	1		*FRT GRILLE BASE	Cracked	645.80 FL	*645.80 FL
22	1		*FRT GRILLE BASE BRACKET RH	Not Necessary	69.80 FL	*- FL
23	1		*FRT GRILLE BASE BRACKET LH	Not Necessary	69.80 FL	*- FL
24	1		*FRT GRILLE LOGO BASE	Not Necessary	145.20 FL	*- FL
25	1		*FRT GRILLE LOGO 3D	Cut	583.40 FL	*395.00 FL
26	1		*FRT GRILLE CHROME MLDG RH	Not Necessary	385.90 FL	*- FL
27	1		*FRT GRILLE CHROME MLDG LH	Not Necessary	385.90 FL	*- FL
28	1		*FRT FORWARD CAMERA	Not Necessary	1,280.00 FL	*- FL
29	1		*FRT BUMPER TOP	Deformed	722.00 FL	*385.00 FL
30	1		*FRT BUMPER SPONGE	Not Necessary	235.90 FL	*- FL
31	1		*FRT RADIATOR SUPPORT PANEL	Not Necessary	1,225.00 FL	*- FL
32	1		*FRT AC AIR GUIDE LOW CENTRE	Not Necessary	185.90 FL	*- FL
33	1		*FRT BONNET LOCK BRACKET	Not Necessary	98.50 FL	*- FL
34	2		*FRT FENDER INNERSHIELD	Not Necessary	446.00 FL	*- FL
35	2		*FRT HEADLAMP	Not Necessary	7,930.00 FL	*- FL
36	2		*FRT HEADLAMP LOW BRACKET	Not Necessary	257.00 FL	*- FL
37	1		*FRT INTAKE AIR DUCT	Not Necessary	164.00 FL	*- FL
38	1		*FRT INTAKE AIR RESONATOR BOX	Not Necessary	120.00 FL	*- FL
39	1		*FRT BONNET WEATHERSTRIP	Cut	125.80 FL	*125.80 FL
40	1		*FRT AC CONDENSER	Not Necessary	1,145.20 FL	*- FL
41	1		*FRT SUPPORT PANEL	Not Necessary	987.50 FL	*- FL
42	1		*FRT RADIATOR	Not Necessary	1,197.00 FL	*- FL
43	1		*FRT RADIATOR FAN ASSY	Not Necessary	1,249.00 FL	*- FL
44	1		*FRT RADIATOR SPARE TANK	Not Necessary	167.00 FL	*- FL
45	1		*FRT RADIATOR SPARE TANK BRACKET	Not Necessary	82.00 FL	*- FL
46	1		*FRT HORN RH	Not Necessary	177.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRT HORN LH	Not Necessary	102.00 FL	*- FL
48	1		*FRT WIPER WASHER TANK	Not Necessary	162.00 FL	*- FL
49	1		*FRT WIPER WASHER TANK PUMP	Not Necessary	104.00 FL	*- FL
50	1		*FRT NUMBER PLATE	Not Necessary	65.00 FS	*- FS
51	20		*FRT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
52	20		*FRT GRILLE CLIP	Necessary	80.00 FS	*20.00 FS
53	20		*FRT BUMPER RIVET	Necessary	80.00 FS	*30.00 FS
54	20		*FRT FENDER INNERSHIELD CLIP	Not Necessary	80.00 FS	*- FS
55	10		*FRT BUMPER INSULATOR CLIP	Not Necessary	40.00 FS	*- FS
56	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
					Sub Total (S\$)	27,872.30 2,768.10
					- List Item Discount on L Items 20.00/20.00% (S\$)	5,473.46 537.62
					Total Parts (S\$)	22,398.84 2,230.48

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,600.00	300.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA	New	1,600.00	350.00
3	TO APPLY CARAMIC COATING	New	488.00	200.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	200.00	30.00
5	TO CONDUCT ANTI RUST TO TUFF COAT	New	100.00	0.00
6	TO REFOCUS HEADLAMP	New	180.00	0.00
7	TO RESET ADAS FAULTY CODE	New	350.00	300.00
Gross Labour Cost (S\$)			4,518.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >