

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22007936/AVCE2**Date:** 21/11/2022**REFERENCE**

Insured/Claimant:	HENG CHENG HUA	Policy No:	2100503266		
Date of Loss:	18/08/2022	Nature of Claim:	OD	Claim No:	2895856303SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM1828L		
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR025299
Reg. Date:	10/03/2017 (Man. Year: 2016)	Chassis No:	WAUZZZ4M1HD027689
Colour:	White	Odometer:	167209 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$156,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,828.00	20,776.56	19,051.44	47.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,074.00	8,402.00	8,672.00	50.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	56,902.00	29,178.56	27,723.44	48.72
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	56,402.00	28,678.56	27,723.44	49.15
+ GST 7.00/7.00% (S\$)	3,948.14	2,007.50	1,940.64	49.15
Nett Amount (S\$)	60,350.14	30,686.06	29,664.08	49.15

INSPECTION

Date of Assignment:	19/08/2022		
Date Inspected:	18/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,896.00 FS	*2,316.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	468.00 FS	*- FS
3	1		*FRONT BUMPER TOW EYE COVER	Necessary	44.00 FS	*35.12 FS
4	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	75.00 FS	*- FS
5	1		*FRONT BUMPER END CAP - RH	Not Necessary	40.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	309.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	230.00 FS	*- FS
8	1		*FRONT BUMPER UNDERRUN BAR - LOWER	Deformed	899.00 FS	*719.20 FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	235.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER - RH	Cracked	235.00 FS	*187.60 FS
11	1		*FRONT BUMPER OUTER SPOILER - RH	Not Necessary	49.00 FS	*- FS
12	1		*RADIATOR GRILLE	Not Necessary	2,741.00 FS	*- FS
13	1		*RADIATOR GRILLE COVER	Not Necessary	81.00 FS	*- FS
14	1		*FRONT BUMPER INNER COVER	Not Necessary	69.00 FS	*- FS
15	1		*FRONT AIR GUIDE GRILLE -RH	Deformed	332.00 FS	*265.60 FS
16	1		*FRONT AIR GUIDE GRILLE END CAP - RH	Not Necessary	38.00 FS	*- FS
17	1		*FRONT INNER SPOILER - RH	Not Necessary	65.00 FS	*- FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	192.00 FS	*153.20 FS
19	1		*FRONT BUMPER CARRIER	Not Necessary	1,025.00 FS	*- FS
20	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	50.00 FS	*39.52 FS
21	1		*FRONT BUMPER SENSOR SUPPORT - LH / RH	O/S Damaged	81.00 FS	*32.00 FS
22	1		*FRONT BUMPER TOP COVER	Not Necessary	146.00 FS	*- FS
23	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
24	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
25	1		*HORN HIGH TONE - RH	Not Necessary	240.00 FS	*- FS
26	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
27	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
28	1		*FRONT FENDER - RH	Repair	1,819.00 FS	*- FS
29	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	79.00 FS	*- FS
30	1		*FRONT FENDER BRACE	Bent	171.00 FS	*136.80 FS
31	1		*FRONT FENDER BRACKET - RH	Not Necessary	72.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	260.00 FS	*- FS
33	1		*WHEEL HOUSING LINER - RH REAR	Not Necessary	260.00 FS	*- FS
34	1		*BONNET	Dented	7,032.00 FS	*5,625.60 FS
35	1		*BONNET IMPACT PROTECTION	Necessary	119.00 FS	*95.20 FS
36	1		*BONNET STRIKER PLATE - RH	Not Necessary	131.00 FS	*- FS
37	1		*BONNET LID LOCK - RH	Not Necessary	243.00 FS	*- FS
38	1		*HEADLIGHT TRIM COVER - RH	Not Necessary	114.00 FS	*- FS
39	1		*FRONT ENGINE HOOD TRIM COVER - RH	Not Necessary	50.00 FS	*- FS
40	1		*HEADLIGHT MOUNTING - RH	Cracked	132.00 FS	*105.20 FS
41	1		*HEADLIGHT	Cracked	10,660.00 FS	*8,528.00 FS
42	1		*HEADLIGHT COOLING FAN - RH	Not Necessary	428.00 FS	*- FS
43	1		*HEADLIGHT POWER MODULE - RH	Not Necessary	842.00 FS	*- FS
44	1		*HEADLIGHT CONTROL UNIT - RH	Not Necessary	840.00 FS	*- FS
45	1		*HEADLIGHT VENT HOSE - RH	Not Necessary	45.00 FS	*- FS
46	1		*LIFT CYLINDER - RH	Cracked	217.00 FS	*173.60 FS
47	1		*LIFT CYLINDER HOSE	Not Necessary	113.00 FS	*- FS
48	1		*FRONT WHEEL COVER - LH	Necessary	607.00 FS	*485.60 FS
49	1		*FRONT WHEEL COVER - RH	Necessary	607.00 FS	*485.60 FS
50	1		*FRONT DOOR COVER - RH	Repair	734.00 FS	*- FS
51	1		*FRONT UNDERBODY NOISE INSULATION	Not Necessary	725.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*RADIATOR SUPPORT BAFFLE - RH	Not Necessary	33.00 FS	*- FS
53	1		*RADIATOR SUPPORT AIR DUCT - UPPER	Not Necessary	48.00 FS	*- FS
54	1		*RADIATOR SUPPORT AIR DUCT - LOWER	Not Necessary	48.00 FS	*- FS
55	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
56	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
57	1		*HORN BRACKET (Supplementary)	Bent	33.00 FS	*25.76 FS
58	1		*FRONT LOCK CARRIER (Supplementary)	Cracked	1,335.00 FS	*1,068.00 FS
59	1		*COOLANT (Supplementary)	Necessary	297.00 FS	*237.12 FS
60	1		*WIRE CONNECTOR (Supplementary)	Damaged	68.00 FS	*54.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	39,828.00	20,776.56
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	300.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,600.00	1,200.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION	New	480.00	480.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
7	TO RESPRAY FRONT BUMPER, RHS FRONT BUMPER LOWER SPOILER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS	New	6,000.00	2,150.00
8	TO REMOVE AND RENEW AIRCON CONDENSER,CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (Supplementary)	New	1,800.00	1,800.00
9	TO RENEW FRONT LOCK CARIER AND ALIGN TO POSITION. (Supplementary)	New	3,600.00	1,800.00
Gross Labour Cost (S\$)			17,074.00	8,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >