

COMFORT TRANSPORTATION PTE LTD**REPAIR ESTIMATE****Vehicle No. :** SHA1097P**Make :** HYUNDAI**Model :** I-40**Date:** 18/08/2022**Insurance:** NTUC**MVA:** MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>X Repair</i>			\$ 553.00
1	REAR BUMPER CLIPS <i>X</i>			\$ 22.00
1	REAR BUMPER LOWER COVER <i>X</i>			\$ 228.00
1	REAR BUMPER REINFORCEMENT <i>X</i>			\$ 428.40
	SUB TOTAL			\$ 1,231.40
	LESS 20%			\$ 246.28
	DISCOUNTED TOTAL			\$ 985.12
	REAR BUMPER REVERSE SENSOR <i>X</i>			\$ 135.70
				\$ 135.70
	Labour Charge			
	PANEL BEATING			\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 660.00
	ESTIMATE TOTAL			\$ 1,780.82

Nett

Nett

280
250
X

530

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1 Day
4/5
Good King
3230 pm
18/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices to be put on a "no haggle" basis
- Third party to be involved on a "no haggle" basis
- No illegal modification to be carried out
- Supplement to be provided and is subject to the approval of the Insurance Company

Acknowledged by Repairer

Signature:

Date: