



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3648X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT DOOR LH	TO REPAIR SEE LABOUR	2,707.70	-
1	ROCKER COVER GARNISH LH	CRACKED	732.80	732.80
	LESS 20% DISCOUNT		-688.10	-146.56
			2,752.40	586.24
	<b><u>NETT ITEMS</u></b>			
1	RR DOOR COMFORT APP LOGO LH (N)	SCRATCHED	80.00	80.00
1	FRT DOOR COMFORT LOGO LH (N)	SCRATCHED	75.00	75.00
	LESS 10% DISCOUNT		-	-15.50
			155.00	139.50
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT DOOR LH.		900.00	280.00
	SPRAY PAINTING CHARGE.		1,000.00	750.00
	TRANSFER OF FRT DOOR.	NOT NECESSARY	120.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
			2,080.00	1,030.00
	<b>GRAND TOTAL</b>		<b>4,987.40</b>	<b>1,755.74</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,400.00</b>

Report Ref No. NS/INC22007942/Gvce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.