

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS22007948/ANY3E2**Date:** 19/04/2023REFERENCE

Insured/Claimant:	CHUA KOON CHUA	Policy No:	SP2001218400-001	
Date of Loss:	16/08/2022	Nature of Claim:	OD	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCK6911M		Engine No:	8ARZ113667
Make & Model:	TOYOTA HARRIER, 2.0 (A)		Chassis No:	JTEZB3GH10J001632
Reg. Date:	28/03/2018 (Man. Year: 2018)		Odometer:	102634 km
Colour:	Silver			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	S\$110,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,846.27	5,974.12	17,872.15	74.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,690.00	1,700.00	3,990.00	70.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,536.27	7,674.12	21,862.15	74.02
Approved Total (Overridden) (S\$)		6,100.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	28,936.27	5,500.00	23,436.27	80.99

INSPECTION

Date of Assignment:	19/08/2022	
Date Inspected:	23/08/2022	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCK6911M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,398.60 FL	*1,850.00 FL
2	1		*TAIL GATE LAMP	O/S Cracked	1,791.20 FL	*425.00 FL
3	1		*TAIL GATE OUTER GARNISH	Deformed	845.20 FL	*688.00 FL
4	1		*TAILGATE LOGO INNER HOLDER	Not Necessary	135.80 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	98.70 FL	*98.70 FL
6	1		*TAILGATE EMBLEM HARRIER	Necessary	98.60 FL	*98.60 FL
7	1		*TAILGATE EMBLEM TURBO	Necessary	95.30 FL	*95.30 FL
8	1		*TAILGATE INNER LOCK	Not Necessary	945.20 FL	*- FL
9	1		*TAILGATE LOCK BOTTOM (OUTER)	Not Necessary	48.90 FL	*- FL
10	1		*TAILGATE DETECTOR	Not Necessary	398.70 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Cut	458.90 FL	*331.00 FL
12	2		*TAILGATE STOPPER	Not Necessary	65.20 FL	*- FL
13	1		*TAILGATE INNER TRIM (LOWER)	Not Necessary	703.60 FL	*- FL
14	2		*TAILGATE SIDE SENSOR	Not Necessary	2,091.60 FL	*- FL
15	1		*TAILGATE WINDSCREEN MOULDING	Necessary	219.80 FL	*219.80 FL
16	1		*TAILGATE WINDSCREEN INNERSEAL	Necessary	60.00 FL	*60.00 FL
17	2		*TAIL GATE DAMPER	Not Necessary	451.20 FL	*- FL
18	1		*REAR BUMPER (UPPER)	Deformed	1,398.60 FL	*904.00 FL
19	1		*REAR BUMPER (LOWER)	Deformed	496.30 FL	*496.30 FL
20	2		*REAR BUMPER REFLECTOR	Not Necessary	179.20 FL	*- FL
21	2		*REAR BUMPER CORNER RETAINER	Not Necessary	196.40 FL	*- FL
22	1		*REAR BUMPER SIDE RETAINER	O/S Damaged	179.20 FL	*89.60 FL
23	1		*REAR BUMPER SPONGE	Cracked	305.80 FL	*122.00 FL
24	2		*TAIL LAMP	Not Necessary	1,791.20 FL	*- FL
25	2		*TAIL LAMP PANEL	Not Necessary	997.00 FL	*- FL
26	2		*REAR FENDER INNER COWLING	Not Necessary	499.60 FL	*- FL
27	2		*REAR FENDER INNER TRIM	Not Necessary	1,578.60 FL	*- FL
28	1		*REAR FENDER AIR VENT	Not Necessary	175.30 FL	*- FL
29	1		*REAR END PANEL	Dented	798.40 FL	*798.40 FL
30	1		*REAR END PANEL DAMPER	Not Necessary	1,385.90 FL	*- FL
31	2		*REAR END PANEL DAMPER BRACKET	Not Necessary	551.20 FL	*- FL
32	1		*REAR END PANEL TOP GARNISH	Deformed	345.80 FL	*345.80 FL
33	2		*REAR FLOOR SIDE PANEL	Not Necessary	999.00 FL	*- FL
34	1		*REAR FLOOR PANEL	Not Necessary	987.50 FL	*- FL
35	1		*REAR FLOOR PANEL TOP BOARD (OUTER)	Deformed	895.70 FL	*718.00 FL
36	1		*REAR FLOOR PANEL TOP BOARD (INNER)	Not Necessary	575.80 FL	*- FL
37	2		*REAR FLOOR PANEL SIDE TRAY (INNER)	Not Necessary	851.20 FL	*- FL
38	2		*REAR FLOOR PANEL SIDE TRAY (OUTER)	Not Necessary	971.40 FL	*- FL
39	1		*REAR FLOOR PANEL BOTTOM SPONGE	Not Necessary	311.80 FL	*- FL
40	1		*REVERSE SENSOR (4PCS)	Damaged (1Pc Only)	1,591.60 FL	*285.00 FL
41	4		*REVERSE SENSOR HOLDERS	Necessary	225.20 FL	*100.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REVERSE SENSOR WIREHARNESS	Not Necessary	987.50 FL	*- FL
43	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
44	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
45	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Not Necessary	50.00 FS	*- FS
46	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
47	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
48	2		*SET TAILLAMP CLIP	Not Necessary	60.00 FS	*- FS
49	2		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
50	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
51	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
52	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
53	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	31,391.70	7,905.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,545.43	1,931.38
Total Parts (\$\$)	23,846.27	5,974.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK ON TAILAMP	New	120.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	120.00	50.00
8	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	RESET TAILGATE SYSTEM	New	250.00	0.00
12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	380.00	0.00
Gross Labour Cost (\$\$)			5,690.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >