9/28/22, 4:50 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22007952/KQCQ2

**Date:** 28/09/2022

TP

Odometer:

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No:

Policy No: MP003219

Claimant Vehicle No :

SHD317X

Insured Vehicle No: GBJ5412K

Date of Loss: 12/08/2022 Nature of Claim:

Claim No: M2204313

580127 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD317X

 Make & Model:
 RENAULT LATITUDE, 2.0 CVT ABS (A)
 Engine No:
 M9R8839C002972

 Reg. Date:
 04/03/2016 (Man. Year: 2015)
 Chassis No:
 VF1ABL15AUC282370

Colour: Metallic White/Red

Engine Capacity: 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Firenza 8 mm Rear Left Side: Sailun 6 mm
Front Right Side: Firenza 8 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,801.86	4,348.64	7,453.22	63.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,240.00	980.00	9,260.00	90.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,041.86	5,328.64	16,713.22	75.82
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	22,041.86	4,250.00	17,791.86	80.72
+ GST 7.00/7.00% (S\$)	1,542.93	297.50	1,245.43	80.72
Nett Amount (S\$)	23,584.79	4,547.50	19,037.29	80.72

**INSPECTION** 

Date of Assignment: 24/08/2022

Trans-Cab Services Pte Ltd (HQ)

Date Inspected: 16/08/2022 Inspected At: 2 Ang Mo Kio Street 63

Cingapara F60111

Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/28/22, 4:50 PM Adjuster Report

## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2022)

Parts: 143 RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD317X)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty Part No	. Particulars	Condition	Repairer's	Amount
1	1	*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
2	1	*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
3	1	*BONNET	Repair	1,312.70 FL	*- FL
4	1	*BONNET HINGE LH	Repair	237.40 FL	*- FL
5	1	*BONNET HINGE RH	Repair	237.40 FL	*- FL
6	1	*HEADLAMP RH	Serviceable	743.60 FL	*- FL
7	1	*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
8	1	*DOOR MIRROR RH	Dented / Cracked	1,483.40 FL	*1,483.40 FL
9	1	*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
10	1	*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
11	1	*BUMPER COVER FRT	Serviceable	747.20 FL	*- FL
12	1	*BUMPER BRACKET KIT FRT RH	Serviceable	101.40 FL	*- FL
13	1	*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
14	1	*FENDER CLIP	Not Necessary	120.00 FS	*- FS
15	1	*FENDER LINER CLIP	Not Necessary	130.00 FS	*- FS
16	1	*FRT BUMPER CLIP	Not Necessary	65.00 FS	*- FS
17	1	*RIM	Serviceable	350.00 FS	*- FS
18	1	*DOOR STICKER TRANS-CAB	Necessary	100.00 FS	*60.00 FS
19	2	*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
20	1	*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
21	1	*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
F=Fra	anchise part. S=Sp	cNett. L=ListItemDisc.	_		
			Sub Total (S\$)	12,974.85	4,825.16
		- List Item Discount on L Items 10.00/10.00% (S\$)			476.52
			Total Parts (S\$)	11,801.86	4,348.64

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	500.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUS AND REALIGN THE SAME	New ST	6,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
	Gross Labor	10,240.00	980.00	
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >