

ASS. REC. BY: Tough

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
☒	☐

Bal. or Market Value: \$ 88K

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: Ms PangVeh No: GLG 9808 SYr Regn: 2017, Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Sprinter 319 2987Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 68793

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB 906633-2P406836Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NP / S/Rim / STD A/Rim orTyre Size: F: 235/60R17R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front:

Rear

R/Bal. 4

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 24/8/22Survey held at Woon Man

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.B. (F

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax 6316 7050
28, Gul Drive, Singapore 629478 Tel: 63531131
(Email Address : woonmeng@singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

To : Budget Direct Insurance
Motor Claims Dept

TP CLAIM

Date : 24 Aug 2022

Fax : 67250853

**RE : ESTIMATE COST FOR MERCEDES BENZ SPRINTER 319- GBG9808S
ACCIDENT INVOLVING GBG9808S & SMM5788E ON 06/08/2022**

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 1,115.26 <i>de ✓</i>
2	Rear running board	1pc	\$ 805.33 <i>de ✓</i>
3	Rear bumper reinforcement	1pc	\$ 587.41 <i>ht ✓</i>
4	Rear bumper rivet @\$4.24ea	7pcs	\$ 29.68 <i>nee ✓</i>
5	Rear wiring harness	1pc	\$ 394.20 <i>Xnn</i>
6	Rear sensor @\$297.27ea	4pcs	\$ 1,189.08 <i>nw ✓</i>
		3726	\$ 4,120.96
	Less 10%		\$ (412.09)
		3726.76	\$ 3,708.87
		3354.08	
	<u>Labour Charge & Misc</u>		
	To remove, replace, repair, weld rear damaged parts	}	\$ 800.00 <i>450</i>
		}	
	To R & R sensor wiring.		\$ 100.00 <i>40</i>
Total			\$ 4,608.87

490

3354.08

490

\$3844.08

3 days

All prices quoted are subjected to GST.

This is a computer generated document. No signature is required.

To Tanfui 97495749
Wp/ 24/8/22 @ 4pm
PIP Repairing new parts
- 3 days
tanfui@lkharts.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer