

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22007973/KCY3E2**Date:** 29/11/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961115
Claimant Vehicle No :	SMS2584P	Insured Vehicle No :	SLN7284K
Date of Loss:	02/08/2022	Nature of Claim:	TP
		Claim No:	281110

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS2584P		
Make & Model:	MERCEDES-BENZ CLA200, 1.3 PROGRESSIVE (R18 LED) (A)	Engine No:	28291480294637
Reg. Date:	19/02/2020 (Man. Year: 2019)	Chassis No:	W1K1183872N080975
Colour:	Metallic Grey	Odometer:	47687 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,584.30	5,362.20	2,222.10	29.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,270.00	1,500.00	54.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,354.30	6,632.20	3,722.10	35.95
+ GST 7.00/7.00% (S\$)	724.80	464.25	260.55	35.95
Nett Amount (S\$)	11,079.10	7,096.45	3,982.65	35.95

INSPECTION

Date of Assignment:	22/08/2022	
Date Inspected:	22/08/2022	Inspected At: Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2022)

Parts: 143 MERCEDES-BENZ CLA200 1.3 PROGRESSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS2584P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,040.00 FN	*- FN
2	1		*HEADLAMP ASSY - LH	Mtg Cracked	3,545.00 FN	*3,545.00 FN
3	1		*FRONT FENDER -LH	Bent	688.00 FN	*688.00 FN
4	1		*FRONT FENDER INNER SHIELD - LH	Serviceable	219.00 FN	*- FN
5	20		*FRONT FENDER INNER SHIELD CLIPS - LH	Not Necessary	180.00 FN	*- FN
6	1		*FRONT BUMPER	Buckled	1,510.00 FN	*1,480.00 FN
7	1		*FRONT BUMPER SIDE RETAINER - LH	Distorted	38.00 FN	*38.00 FN
8	6		*FRONT BUMPER SENSOR SEALS	Necessary	72.00 FN	*72.00 FN
9	15		*FRONT BUMPER CLIPS	Necessary	135.00 FN	*135.00 FN
					Sub Total (\$\$)	8,427.00 5,958.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	842.70 595.80
					Total Parts (\$\$)	7,584.30 5,362.20

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX FRONT BUMPER SENSOR	New	100.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT & STRAIGHTEN LH FRONT FENDER INNER PANEL, LH FRONT CHASSIS FRAME. INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	800.00	500.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	660.00
5	TO RESET AND RE-PROGRAMME HEADLAMP FAULT CODE	New	350.00	0.00
6	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	120.00	30.00
7	TO COMPUTERISE CHECK WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$)			2,770.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >