

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22007979/UCY3Q2**Date:** 29/09/2022**REFERENCE**

Insured/Claimant: SOON HOCK SPRINKLER SYSTEM PTE. LTD. Policy No: DMCVSNW00143472100
Date of Loss: 18/08/2022 Nature of Claim: OD Claim No: SNM22D205816/C01/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK162J**
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2860551
Reg. Date: 25/11/2019 (Man. Year: 2019) Chassis No: JTFAT35Y90K213746
Colour: White Odometer: 144128 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$72,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
Front Left Side: Maxmiler 5 mm Rear Left Side: Delium 3/3 mm
Front Right Side: Maxmiler 5 mm Rear Right Side: Delium 4/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,520.00	1,380.00	140.00	9.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	932.40	848.40	84.00	9.01
Paintwork Labour	403.20	403.20	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,855.60	2,631.60	224.00	7.84
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	2,855.60	2,131.60	724.00	25.35
+ GST 7.00/7.00% (S\$)	199.89	149.21	50.68	25.35
Nett Amount (S\$)	3,055.49	2,280.81	774.68	25.35

INSPECTION

Date of Assignment: 19/08/2022 Present Location: Jin Auto Services Pte Ltd (Defu)
Date Inspected: 22/08/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)
Estimated Period of Repair: 5.0 days Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Sep 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK162J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		1,520.00 F	*1,380.00 F
						F=Franchise part.
Total Parts (S\$)					1,520.00	1,380.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT LABOUR CHARGE	New	403.20	403.20
<u>Labour Items</u>				
2	TOTAL LABOUR CHARGE	New	932.40	848.40
Gross Labour Cost (\$\$)			1,335.60	1,251.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >