

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/EG122007981/TCY3M4**Date:** 23/03/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKV4192G**Insured Vehicle No :** SKV6836U

Date of Loss: 09/08/2022

Nature of Claim:

TP

Claim No: CDMPG22001696

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKV4192G**

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A)

Engine No: 4J11YB3529

Reg. Date: 09/05/2018 (Man. Year: 2018)

Chassis No: GF7W0401628

Colour: White

Odometer: 92472 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,400.00	0.00	1,400.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	500.00	500.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	2,400.00	500.00	1,900.00	79.17

INSPECTION

Date of Assignment: 18/08/2022

Date Inspected:

22/08/2022

Inspected At:

Ceramicworks (HQ)

13 Kaki Bukit Road 4, #01-29, Bartley Biz Centre
Singapore 417807

Estimated Period of Repair:

2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2023)
Parts:	M1-SUV	mitsubishi outlander 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV4192G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	816.00 F	*- F
2	1		*REAR BUMPER CLIPS	Not Necessary	30.00 F	*- F
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	64.00 F	*- F
4	2		*REAR BUMPER IMPACT BRACKET	Not Necessary	210.00 F	*- F
5	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,400.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	100.00
2	SPRAY PAINTING	New	500.00	400.00
3	TO REMOVE REVERSE SENSOR	New	100.00	0.00
Gross Labour Cost (\$)			1,000.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >