

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS22007983/RCY3Q2**Date:** 29/09/2022**REFERENCE****Insured/Claimant:** CHANG CHIZ HAU(ZHANG ZHIHAO)**Policy No:** SP2002380678**Date of Loss:** 17/08/2022**Nature of Claim:** OD**Claim No:** 202222006182**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SLP2074Y**Make & Model:** VOLKSWAGEN GOLF R, 2.0 (A)**Engine No:** DFY406442**Reg. Date:** 15/07/2022 (Man. Year: 2022)**Chassis No:** WVWZZZCDZNW160623**Colour:** Blue**Odometer:** 3161 km**Engine Capacity:** 1498 cc**Market Value/New Car Price:** S\$188,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes **Engine Modification:**

No

Pre-accident Condition:**CONDITION OF TYRES****Front Tyre Size:** 225/40 R18**Rear Tyre Size:** 225/40 R18**Front Left Side:** Bridgestone 6 mm**Rear Left Side:** Bridgestone 6 mm**Front Right Side:** Bridgestone 6 mm**Rear Right Side:** Bridgestone 6 mm*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,170.98	3,194.49	1,976.49	38.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,190.00	2,540.00	5,650.00	68.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,360.98	5,734.49	7,626.49	57.08
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,760.98	5,134.49	7,626.49	59.76
+ GST 7.00/7.00% (S\$)	893.27	359.41	533.86	59.76
Nett Amount (S\$)	13,654.25	5,493.90	8,160.35	59.76

INSPECTION**Date of Assignment:** 19/08/2022**Date Inspected:** 22/08/2022 **Inspected At:**

Volkswagen Group Singapore Pte Ltd

247 ALEXANDRA ROAD

Singapore 159934

Estimated Period of Repair: 6.0 days**Adjuster:** MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2022)
Parts:	143	VOLKSWAGEN GOLF R 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP2074Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Deformed	917.24 FS	*917.24 FS
2	1		*FOAM INSERT	Not Necessary	36.04 FS	*- FS
3	1		*IMPACT BEAM REINFORCEMENT	Not Necessary	433.32 FS	*- FS
4	4		*POP-RIVET	Necessary	7.60 FS	*7.60 FS
5	1		*SUPPORT PART BUMPER INNER BRACKET LH	Not Necessary	42.98 FS	*- FS
6	1		*SUPPORT PART BUMPER INNER BRACKET RH	Not Necessary	42.98 FS	*- FS
7	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	19.23 FS	*- FS
8	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	19.23 FS	*- FS
9	4		*EXPANDING NUT	Not Necessary	5.70 FS	*- FS
10	1		*RADIATOR GRILLE BLACK	Cracked	496.20 FS	*496.20 FS
11	1		*VW SIGN BLACK BRIGHT CHRO	Necessary	101.68 FS	*101.68 FS
12	1		*COOLING AIR GRILLE BLACK BUMPER LOWER GRILLE (CTR)	Not Necessary	178.04 FS	*- FS
13	1		*COOLING AIR GRILLE BLACK BUMPER LOWER GRILLE (LH)	Not Necessary	76.32 FS	*- FS
14	1		*COOLING AIR GRILLE BLACK BUMPER LOWER GRILLE (RH)	Not Necessary	76.32 FS	*- FS
15	1		*DECORATIVE MOULDING BLACK BUMPER LOWER MLDG BLACK (CTR)	Not Necessary	110.31 FS	*- FS
16	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,033.92 FS	*1,033.92 FS
17	1		*REAR DIFFUSOR BLACK REAR BUMPER SPOILER	Scratched	269.05 FS	*269.05 FS
18	4		*RIVET	Necessary	3.80 FS	*3.80 FS
19	2		*SENSOR BRACKET	Necessary	18.56 FS	*18.56 FS
20	1		*SENSOR BRACKET	Necessary	9.28 FS	*9.28 FS
21	1		*SENSOR BRACKET	Necessary	9.28 FS	*9.28 FS
22	1		*BONDING AGENT FOR PLASTIC	Necessary	49.57 FS	*49.57 FS
23	1		*2K-PLASTIC ADHESIVE	Necessary	61.88 FS	*61.88 FS
24	1		*BUMPER REAR REINFORCEMENT	Not Necessary	390.32 FS	*- FS
25	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	49.13 FS	*- FS
26	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	30.16 FS	*- FS
27	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	30.16 FS	*- FS
28	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	30.16 FS	*- FS
29	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	30.16 FS	*- FS
30	1		*DECORATIVE MOULDING BRIGHT LHR BUMPER LOWER MLDG CHROM	Not Necessary	59.26 FS	*- FS

Report was unsubmitted during this print-out.

9/29/22, 10:41 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*DECORATIVE MOULDING BRIGHT RHR BUMPER LOWER MLDG CHROM	Not Necessary	59.26 FS	*- FS
32	2		*LED LICENCE PLATE LIGHT	Not Necessary	92.26 FS	*- FS
33	1		*REFLECTOR RH	Not Necessary	56.91 FS	*- FS
34	1		*INSCRIPTION BRIGHT CHROME BOOT LID NAME PLATE -GOLF	Not Necessary	54.12 FS	*- FS
35	1		*INSCRIPTION BRIGHT CHROME BOOT LID NAME PLATE -ETSI	Not Necessary	54.12 FS	*- FS
36	1		*NAME PLATE FRT	Bent	80.00 FS	*80.00 FS
37	1		*NAME PLATE REAR	Bent	80.00 FS	*80.00 FS
38	1		*RADIATOR GRILLE (R-LINE LOGO)	Necessary	56.43 FS	*56.43 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$)	5,170.98 3,194.49
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FRT	New	1,680.00	560.00
2	SPRAY PAINT FRT	New	1,590.00	530.00
3	LABOUR REAR	New	2,240.00	560.00
4	SPRAY PAINT REAR	New	2,120.00	530.00
5	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	200.00	0.00
6	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
Gross Labour Cost (\$)			8,190.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >