

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIS22007984/RPA3Q2**Date:** 12/01/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000514848-01
Claimant Vehicle No :	SNB837B	Insured Vehicle No :	SLR8256P
Date of Loss:	18/08/2022	Nature of Claim:	TP
		Claim No:	202222006232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB837B		
Make & Model:	VOLKSWAGEN TIGUAN, 1.4 TSI (A)	Engine No:	CZDB20395
Reg. Date:	29/07/2021 (Man. Year: 2020)	Chassis No:	WVGZZZ5NZLW393877
Colour:	Black	Odometer:	15148 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,684.24	2,805.43	1,878.81	40.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	3,960.00	1,000.00	20.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,644.24	6,765.43	2,878.81	29.85
+ GST 7.00/7.00% (S\$)	675.10	473.58	201.52	29.85
Nett Amount (S\$)	10,319.34	7,239.01	3,080.33	29.85
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		150.00		
Nett Liability (S\$)		7,712.01		

INSPECTION

Date of Assignment:	24/08/2022		
Date Inspected:	24/08/2022	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2023)
Parts:	M1-SUV	VOLKSWAGEN TIGUAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB837B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER FOR BUMPER PRIMED REAR BUMPER (UPPER)	Deformed	1,427.64 FS	*1,427.64 FS
2	1	*SPOILER PRIMED BUMPER LOWER SPOILER	Deformed	392.85 FS	*392.85 FS
3	1	*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	40.73 FS	*- FS
4	1	*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	40.73 FS	*- FS
5	1	*GUIDE PIECE LHR BUMPER BRACKET (OUTER)	Not Necessary	40.73 FS	*- FS
6	1	*GUIDE PIECE RHR BUMPER BRACKET (OUTER)	Not Necessary	40.73 FS	*- FS
7	1	*ATTACHMENT STRIP REAR BUMPER BRACKET (CTR)	Necessary	63.67 FS	*63.67 FS
8	4	*SENSOR PRIMED	Not Necessary	684.65 FS	*- FS
9	1	*SEAL RING SATIN BLACK (4 PCS)	Necessary	16.99 FS	*16.99 FS
10	1	*SENSOR BRACKET	Necessary	12.77 FS	*12.77 FS
11	1	*SENSOR BRACKET	Necessary	12.77 FS	*12.77 FS
12	1	*SENSOR BRACKET	Necessary	12.77 FS	*12.77 FS
13	1	*SENSOR BRACKET	Necessary	12.77 FS	*12.77 FS
14	1	*2K-PLASTIC ADHESIVE	Necessary	77.35 FS	*77.35 FS
15	1	*BONDING AGENT FOR PLASTIC	Necessary	61.97 FS	*61.97 FS
16	1	*BUMPER REINFORCEMENT	Not Necessary	703.85 FS	*- FS
17	1	*DECORATIVE MOULDING BRIGHT BUMPER CHROME (CTR)	Scratched	210.38 FS	*210.38 FS
18	1	*DECORATIVE MOULDING BRIGHT LHR BUMPER CHROME	Not Necessary	161.93 FS	*- FS
19	1	*DECORATIVE MOULDING BRIGHT RHR BUMPER CHROME	Not Necessary	165.46 FS	*- FS
20	1	*REAR DIFFUSOR BLACK	Deformed	503.50 FS	*503.50 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 4,684.24 2,805.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	2,160.00	1,440.00
2	SPRAY PAINTING	New	2,040.00	2,040.00
3	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (\$\$)			4,960.00	3,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >