



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1749S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FRONT BUMPER TOP BRACKET LH / RH @\$22.40	NECESSARY	44.80	44.80
1	FRONT BUMPER	CUT	1,052.20	1,052.20
1	FRONT RADIATOR GRILLE	CUT	1,480.00	1,480.00
1	FRONT GRILLE EMBLEM	SERVICEABLE	129.50	-
1	HEAD LAMP LH	SERVICEABLE	1,388.00	-
1	FRONT BUMPER GRILLE LH	CUT	187.20	187.20
10	BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-860.74	-557.24
			3,442.96	2,228.96
	<u>LABOUR</u>			
	PANEL BEATING.		450.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.		60.00	30.00
	CHECK LIGHTING.		60.00	30.00
			870.00	590.00
	GRAND TOTAL		4,312.96	2,818.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,250.00

Report Ref No. NS/INC22007990/Vvce2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.