



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8999E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER TOP BRACKET LH/RH	NECESSARY	44.80	44.80
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,052.20	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	663.00	-
1	HEAD LAMP RH	SERVICEABLE	1,388.00	-
1	FRONT BUMPER GRILLE RH	SERVICEABLE	187.20	-
10	BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-671.44	-13.36
			2,685.76	53.44
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT FENDER ADVERTISEMENT (SN)	NOT NECESSARY	100.00	-
			100.00	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER RH.		450.00	280.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	30.00
	CHECK LIGHTING.		60.00	30.00
			1,170.00	840.00
	<b>GRAND TOTAL</b>		<b>3,955.76</b>	<b>893.44</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>700.00</b>

Report Ref No. NS/INC22007991/Vvcm4

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.