

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7152Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER COVER	CUT	481.10	481.10
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET LH	NECESSARY	28.00	28.00
1	FRT BUMPER CENTRE MOULDING UPPER	SCRATCHED	368.50	368.50
1	FRT BUMPER MOULDING LH	SCRATCHED	93.60	93.60
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	949.30	-
1	DAY LIGHT LH	SERVICEABLE	642.50	-
1	HEADLAMP LH	SCRATCHED	2,110.30	2,110.30
1	FRT FENDER LH	DENTED	588.80	588.80
1	EMBLEM - BLUE DRIVE LH	NECESSARY	26.60	26.60
1	FRT WHEEL HUB CAP LH	SCRATCHED	346.40	346.40
1	FRT FENDER SHIELD LH	SERVICEABLE	164.70	-
	LESS 20% DISCOUNT		-1,164.36	-813.06
			4,657.44	3,252.24
	SPECIAL NETT ITEMS			
1	FRT FENDER ADVERTISEMENT STICKER LH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,100.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	30.00
	CHECK LIGHTING / WIRING.		60.00	30.00
			1,820.00	1,260.00
	GRAND TOTAL		6,577.44	4,612.24





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,700.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC22007996/Vce2



THEVAN THOMAS KARTHIKESAVAN

**Asst. Automotive Assessor** 



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.