

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8624L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER BRACKET LH	NECESSARY	55.80	55.80
1	REAR WHEEL COVER LH	SCRATCHED	346.40	346.40
1	REAR DOOR PANEL LH	DENTED	2,147.90	2,147.90
1	REAR DOOR HANDLE LH	SCRATCHED	125.30	125.30
1	REAR FENDER LH	DENTED	1,768.30	1,768.30
	LESS 20% DISCOUNT		-980.62	-888.74
			3,922.48	3,554.96
<u>NETT ITEMS</u>				
1	PETRO STICKER (N)	NECESSARY	25.00	25.00
1	REAR DOOR COMFORT APP (SN)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-10.50	-10.50
			94.50	94.50
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		900.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE / REFIX UPHOLSTERY.		90.00	30.00
	CHECK WIRING.		60.00	30.00
			1,650.00	1,260.00
GRAND TOTAL			5,666.98	4,909.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,000.00

Report Ref No. NS/INC22007997/Vce2



THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.