

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22007999/Vqce2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	07-09-2022 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLM 2929Y	Veh. Ir	spected	SHC 1106L	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1174719-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	06/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU087886	Colou	r	BLUE	
	Odometer	737359	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	206/60 R16	WEST		5 mm	
	L/H Front Tyre	206/60 R16	WEST		5 mm	
	R/H Rear Tyre	206/60 R16	WEST	LAKE	5 mm	
	L/H Rear Tyre	206/60 R16	WEST	_AKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/06/2022	Inspec	tion Date	06/06/2022	
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					