

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008006/UPA3Q2**Date:** 12/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070055092
Claimant Vehicle No :	SLF1506C	Insured Vehicle No :	SMS9613T
Date of Loss:	18/08/2022	Nature of Claim:	TP
		Claim No:	2071507023SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF1506C		
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT ABS D/AIRBAG 2WD (A)	Engine No:	L15B31190190
Reg. Date:	16/08/2016 (Man. Year: 2016)	Chassis No:	JHMGK5850HX200301
Colour:	White	Odometer:	87533 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45Z R16	Rear Tyre Size:	205/45Z R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,139.00	3,109.92	1,029.08	24.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	2,090.00	880.00	29.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,109.00	5,199.92	1,909.08	26.85
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	7,109.00	4,100.00	3,009.00	42.33
+ GST 7.00/7.00% (S\$)	497.63	287.00	210.63	42.33
Nett Amount (S\$)	7,606.63	4,387.00	3,219.63	42.33
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,924.00		

INSPECTION

Date of Assignment:	22/08/2022	
Date Inspected:	22/08/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	970.00 FL	*910.50 FL
2	1		*TAILGATE LOCK	Bent / Twisted	224.00 FL	*145.50 FL
3	1		*TAILGATE JAZZ EMBLEM	Necessary	42.00 FL	*16.00 FL
4	1		*TAILGATE GLASS MOULDING	Necessary	162.00 FL	*86.00 FL
5	1		*TAILGATE TRIM BOARD	Necessary	252.00 FL	*252.00 FL
6	1		*SET REVERSE SENSOR (4 PCS)	Shorted	300.00 FL	*300.00 FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	145.00 FL	*145.00 FL
8	1		*TAILGATE INNER HANDLE	Not Necessary	67.00 FL	*- FL
9	1		*REAR BUMPER	Dented / Deformed	928.00 FL	*492.50 FL
10	2		*REAR BUMPER SIDE RETAINER	Bent	50.00 FL	*50.00 FL
11	1		*REAR END PANEL	Dented	490.00 FL	*397.90 FL
12	1		*REAR END PANEL GARNISH	Twisted	125.00 FL	*125.00 FL
13	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
14	1		*TAILGATE BUZZER	Cracked	135.00 FL	*64.50 FL
15	2		*REAR FENDER INNER TRIM	Deformed / Torn	590.00 FL	*590.00 FL
16	1		*TAILGATE SEALANT	Necessary	100.00 FS	*50.00 FS
17	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
18	1		*TAILGATE GLASS INNER SEAL	Necessary	80.00 FS	*40.00 FS
19	1		*TAILGATE TRIM BOARD CLIPS	Necessary	40.00 FS	*40.00 FS
20	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
21	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
22	1		*REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
23	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	5,035.00 3,824.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					896.00	714.98
					Total Parts (\$\$)	4,139.00 3,109.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER TAILGATE GLASS	New	150.00	120.00
2	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
3	RESPRAY ANTI RUST	New	150.00	60.00
4	APPLY BODY SEALANT TO CAR JOINTS	New	150.00	0.00
5	INSTALL REVERSE SENSOR }	New	100.00	50.00
6	TO INSTALL REVERSE CAMERA }	New	150.00	0.00
7	TO CHECK LIGHT SYSTEM AND WIRING	New	50.00	20.00
8	TO REMOVE/REFIX INNER TRIMS ,GARNISH AND ETC TO FACILITATE REPAIRS	New	150.00	80.00
9	WATER TEST TO CHECK FOR LEAKAGE	New	50.00	0.00
10	TO REPAIR INNER PANEL ACCIDENT DAMAGE AREA ,CUT /REWELD REAR END PANEL ,REPLACEMENT OF PARTS AND ALIGN THE SAME	New	900.00	800.00
11	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	1,000.00	900.00
Gross Labour Cost (\$\$)			2,970.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >