

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008008/EVY3M4**Date:** 21/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00087422105

**Claimant Vehicle
No :** SNA4999X**Insured Vehicle
No :** GBC2175B

Date of Loss: 16/08/2022

Nature of Claim: TP

Claim
No: SNM22D205846/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNA4999X**

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A)

Engine No: 4J11AB7858

Reg. Date: 04/01/2019 (Man. Year: 2018)

Chassis No: GF7W0600414

Colour: Red

Odometer: 63046 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R15

Rear Tyre Size: 215/65 R15

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,569.00	4,466.00	5,103.00	53.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,740.00	4,420.00	5,320.00	54.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	19,309.00	8,886.00	10,423.00	53.98
+ GST 7.00/7.00% (\$\$)	1,351.63	622.02	729.61	53.98
Nett Amount (\$\$)	20,660.63	9,508.02	11,152.61	53.98

INSPECTION

Date of Assignment: 22/08/2022

Date Inspected: 13/09/2022 Inspected At:

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
209 PANDAN GARDENS SINGAPORE 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2022)
Parts:	M1-SUV	mitsubishi OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA4999X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR BUMPER	Dented	1,158.00 FS	*1,158.00 FS
2	1		*EXTENSION, RR BUMPER	Crushed	499.00 FS	*499.00 FS
3	1		*BRKT,R/BMPR FACE SIDE,LH	Broken	27.00 FS	*27.00 FS
4	1		*BRKT,R/BMPR FACE SIDE,RH	Not Necessary	27.00 FS	*- FS
5	1		*REINFORCEMENT,RR BUMPER,LH	Not Necessary	95.00 FS	*- FS
6	1		*REINFORCEMENT,RR BUMPER,RH	Not Necessary	95.00 FS	*- FS
7	8		*CLIP,ENG ROOM COVER	Not Necessary	16.00 FS	*- FS
8	1		*MOULDING,RR BUMPER,LH	Broken	128.00 FS	*128.00 FS
9	1		*MOULDING,RR BUMPER,RH	Not Necessary	128.00 FS	*- FS
10	1		*MOULDING,RR WHEEL ARCH,LH	Necessary	162.00 FS	*162.00 FS
11	1		*MOULDING,RR WHEEL ARCH,RH	Not Necessary	223.00 FS	*- FS
12	1		*PANEL ASSY,TAILGATE	Dented	1,378.00 FS	*1,378.00 FS
13	1		*GARNISH,TAILGATE	Not Necessary	691.00 FS	*- FS
14	1		*LATCH,TAILGATE	Not Necessary	482.00 FS	*- FS
15	1		*STRIKER,TAILGATE LATCH	Not Necessary	20.00 FS	*- FS
16	2		*DAM,TAILGATE SIDE	Necessary	66.00 FS	*66.00 FS
17	1		*DAM,TAILGATE,UPR	Necessary	13.00 FS	*13.00 FS
18	4		*FASTENER,WINDSHIELD	Necessary	32.00 FS	*32.00 FS
19	2		*STOPPER,WINDSHIELD GLASS	Necessary	8.00 FS	*8.00 FS
20	1		*DAM,TAILGATE,LWR	Necessary	24.00 FS	*24.00 FS
21	2		*HINGE,TAILGATE	Not Necessary	92.00 FS	*- FS
22	1		*MARK,OUTLANDER	Necessary	115.00 FS	*115.00 FS
23	1		*PANEL,RR END	Not Necessary	454.00 FS	*- FS
24	1		*TRIM,RR END	Not Necessary	114.00 FS	*- FS
25	1		*BOX,CARGO FLOOR	Not Necessary	206.00 FS	*- FS
26	1		*LAMP ASSY,COMB,RR LH	Not Necessary	848.00 FS	*- FS
27	1		*LAMP ASSY,COMB,RR RH	Not Necessary	848.00 FS	*- FS
28	1		*LAMP ASSY,TAIL,LH	Broken	613.00 FS	*613.00 FS
29	1		*LAMP ASSY,TAIL,RH	Not Necessary	613.00 FS	*- FS
30	1		*REFLECTOR,TAIL LAMP,LH	Broken	101.00 FS	*101.00 FS
31	1		*REFLECTOR,TAIL LAMP,RH	Not Necessary	101.00 FS	*- FS
32	1		*BUZZER, KEYLESS OPERATIO, RR	Broken	92.00 FS	*92.00 FS
33	10		*CLIPS	Necessary	20.00 FS	*20.00 FS
34	1		*SUNDRIES	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,569.00	4,466.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW TAILGATE , RR BUMPER & RR END PNL REPAIR LHR FENDER , RHR FENDER & RR FLR PNL	New	3,840.00	1,280.00
2	RESPRAY TAILGATE , RR BUMPER , RR END PNL (LHR FENDER , RHR FENDER & RR FLR PNL	New	3,850.00	1,650.00
3	REMOVE & REFIT TAILGATE COMPONENTS	New	280.00	280.00
4	REMOVE & REFIT RR FLR BOARD , TRIM & CARPET	New	280.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	100.00	100.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
7	REMOVE & REFIT RR WINDSCREEN GLASS	New	320.00	320.00
8	SUPPLY WINDSCREEN SEALANT	New	80.00	80.00
9	SUPPLY RR NUMBER PLATE WITH CASING	New	80.00	0.00
10	REMOVE & REFIT REVERSE SENSOR	New	100.00	80.00
11	SUPPLY REVERSE SENSOR	New	220.00	220.00
12	APPLY ANTI CORROSION ON AFFECTED AREAS	New	180.00	40.00
13	SUPPLY BODY PNL SEALANT	New	80.00	40.00
14	SUPPLY C&C BADGE	New	50.00	50.00
Gross Labour Cost (\$\$)			9,740.00	4,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >