



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Muhammad Shadiq Bin Aziz	Cust No/Name /Mr Muhammad Shadiq Bin Aziz
Blk 799 Yishun Ring Road	Reg No/Reg Date SNA4999X / 04/01/201
#06-3418	Date In/Mileage / 0
Singapore 760799	Chassis No GF7W0600414
Contact No Mobile: 91871714	Engine No 4J11AB7858
	Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	19/08/2022/ 17:22	TLE	261 / Edwin Caina	26347			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000						1780		3840.00
RENEW TAILGATE , RR BUMPER & RR END PNL								
REPAIR LHR FENDER , RHR FENDER & RR FLR PNL 640X7								
E PNT98000						1650		3850.00
RESPRAY TAILGATE , RR BUMPER , RR END PNL 550X3								
LHR FENDER , RHR FENDER & RR FLR PNL								
E PNT88000								280.00
REMOVE & REFIT TAILGATE COMPONENTS								
E PNT88000								280.00
REMOVE & REFIT RR FLR BOARD , TRIM & CARPET								
A 54900099								100.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
E PNT88000								320.00
REMOVE & REFIT RR WINDSCREEN GLASS								
M SUNDRY								80.00
SUPPLY WINDSCREEN SEALANT								
M SUNDRY								80.00
SUPPLY RR NUMBER PLATE WITH CASING								
E PNT88000								100.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								220.00
SUPPLY REVERSE SENSOR								
M SUNDRY								180.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								80.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								50.00
SUPPLY C&C BADGE								
M SUNDRY								80.00
Sundries								
M FACE,RR BUMPER					1.00	1158.00	00.00	1158.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Muhammad Shadiq Bin Aziz	Cust No/Name /Mr Muhammad Shadiq Bin Aziz
Blk 799 Yishun Ring Road	Reg No/Reg Date SNA4999X / 04/01/201
#06-3418	Date In/Mileage / 0
Singapore 760799	Chassis No GF7W0600414
Contact No Mobile: 91871714	Engine No 4J11AB7858
	Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	19/08/2022/ 17:22	TLE	261 / Edwin Caina	26347			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	EXTENSION,RR BUMPER	/ (RM) (S/M)			1.00	499.00	00.00	499.00
M	BRKT,R/BMPR FACE SIDE,LH	/ BR			1.00	27.00	00.00	27.00
M	BRKT,R/BMPR FACE SIDE,RH	X nn			1.00	27.00	00.00	27.00
M	REINFORCEMENT,RR BUMPER,LH	? X nn			1.00	95.00	00.00	95.00
M	REINFORCEMENT,RR BUMPER,RH	? X nn			1.00	95.00	00.00	95.00
M	CLIP,ENG ROOM COVER	X nn			8.00	2.00	00.00	16.00
M	MOULDING,RR BUMPER,LH	/ BR			1.00	128.00	00.00	128.00
M	MOULDING,RR BUMPER,RH	X nn			1.00	128.00	00.00	128.00
M	MOULDING,RR WHEEL ARCH,LH	/ REC			1.00	162.00	00.00	162.00
M	MOULDING,RR WHEEL ARCH,RH	X nn			1.00	223.00	00.00	223.00
M	PANEL ASSY,TAILGATE	/ DD			1.00	1378.00	00.00	1378.00
M	GARNISH,TAILGATE	X nn			1.00	691.00	00.00	691.00
M	LATCH,TAILGATE	X nn			1.00	482.00	00.00	482.00
M	STRIKER,TAILGATE LATCH	X nn			1.00	20.00	00.00	20.00
M	DAM,TAILGATE SIDE	/ REC			2.00	33.00	00.00	66.00
M	DAM,TAILGATE,UPR	/ REC			1.00	13.00	00.00	13.00
M	FASTENER,WINDSHIELD	/ REC			4.00	8.00	00.00	32.00
M	STOPPER,WINDSHIELD GLASS	/ REC			2.00	4.00	00.00	8.00
M	DAM,TAILGATE,LWR	/ REC			1.00	24.00	00.00	24.00
M	HINGE,TAILGATE	X nn			2.00	46.00	00.00	92.00
M	MARK,OUTLANDER	/ REC			1.00	115.00	00.00	115.00
M	PANEL,RR END	? X nn			1.00	454.00	00.00	454.00
M	TRIM,RR END	? X nn			1.00	114.00	00.00	114.00
M	BOX,CARGO FLOOR	? X nn			1.00	206.00	00.00	206.00
M	LAMP ASSY,COMB,RR LH	X nn			1.00	848.00	00.00	848.00
M	LAMP ASSY,COMB,RR RH	X nn			1.00	848.00	00.00	848.00
M	LAMP ASSY,TAIL,LH	/ BR			1.00	613.00	00.00	613.00
M	LAMP ASSY,TAIL,RH	? X nn			1.00	613.00	00.00	613.00
M	REFLECTOR,TAIL LAMP,LH	/ BR			1.00	101.00	00.00	101.00
M	REFLECTOR,TAIL LAMP,RH	X nn			1.00	101.00	00.00	101.00
Store (LKK) 13/9/22, 12.00p								19,309

Confirm & accepted by SURVEYOR NAME :

LKK Auto Consultants henceforth the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory and company stamp

SURVEYOR SIGNATURE :

W R
 P/P, My Bel
 6 days (not include and panel)

Nett 19,197.00
 7% GST on 19197.00 1343.79
 Total Payable 20,540.79

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.