



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7854L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED / TORN	626.70	626.70
1	SET REAR BUMPER CLIPS	NECESSARY	55.00	55.00
2	REAR BUMPER FASCIA SIDE RETAINER LH & RH @ \$66.60	O/S BENT	133.20	66.60
1	REAR BUMPER FASCIA REFLECTOR	NOT NECESSARY	63.40	-
1	REAR BUMPER FASCIA BRACKET	NOT NECESSARY	67.10	-
1	TAIL LAMP RH	CRACKED	375.90	375.90
	LESS 25% DISCOUNT		-	-281.05
			1,321.30	843.15
LABOUR				
	CUT OUT, RENEW, KNOCKING & WELDING REAR FENDER RH, REAR LAMP PANEL RH, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY.		780.00	400.00
	SPRAY PAINTING ON DAMAGE PARTS.		880.00	500.00
	CHECK ALL LIGHTING AFTER REPAIRS.		35.00	20.00
			1,695.00	920.00
GRAND TOTAL			3,016.30	1,763.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,400.00

Report Ref No. CS/INC22008009/Ucy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.