

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI22008013/UCY3Q2**Date:** 02/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00115842100

Claimant Vehicle No : SLN9214A **Insured Vehicle No :** SJJ2262B

Date of Loss: 17/08/2022 Nature of Claim: TP Claim No: SNM22D205818/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN9214A**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4605317

Reg. Date: 26/09/2006 (Man. Year: 2006) Chassis No: MR053ZEC107132172

Colour: Grey Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,449.65	8,180.46	5,269.19	39.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,330.00	4,360.00	1,970.00	31.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,779.65	12,540.46	7,239.19	36.60
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	19,779.65	10,000.00	9,779.65	49.44
+ GST 7.00/7.00% (S\$)	1,384.58	700.00	684.58	49.44
Nett Amount (S\$)	21,164.23	10,700.00	10,464.23	49.44

INSPECTION

Date of Assignment: 21/08/2022

Date Inspected: 22/08/2022 Inspected At: Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN9214A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	794.50 FL	*794.50 FL
2	2		*BOOT LID HINGE	Repair	364.80 FL	*- FL
3	2		*BOOT LID STOPPER	Not Necessary	87.40 FL	*- FL
4	1		*BOOT LID LOCK	Twisted	182.60 FL	*182.60 FL
5	1		*BOOT LID LOCK STRIKER	Twisted	181.55 FL	*181.55 FL
6	1		*BOOT LID LOCK CABLE	Not Necessary	161.40 FL	*- FL
7	1		*BOOT LID WEATHERSTRIPE	Twisted	131.70 FL	*131.70 FL
8	1		*BOOT LID OUTER GARNISH	Cracked	182.25 FL	*182.25 FL
9	3		*BOOT LID OUTER GARNISH CLIPS	Not Necessary	38.70 FL	*- FL
10	1		*BOOT LID OUTER GARNISH BADGE	Necessary	29.80 FL	*29.80 FL
11	1		*BOOT LID EMBLEM ALTIS	Necessary	27.25 FL	*27.25 FL
12	1		*BOOT LID EMBLEM COROLLA	Necessary	28.90 FL	*28.90 FL
13	1		*BOOT LID EMBLEM 1.6	Necessary	27.55 FL	*27.55 FL
14	1		*BOOT LID EMBLEM VVTI	Not fitted	28.50 FL	*- FL
15	2		*BOOT LID REFLECTOR	Cracked	743.50 FL	*743.50 FL
16	2		*BOOT LID REFLECTOR SEALANT	Not Necessary	100.00 FL	*- FL
17	1		*REAR FENDER LH	Badly Dented	981.90 FL	*981.90 FL
18	1		*REAR FENDER AIR VENT	Not Necessary	43.70 FL	*- FL
19	1		*REAR FENDER SPLASH SHIELD	Torn	53.90 FL	*53.90 FL
20	8		*REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	103.20 FL	*- FL
21	2		*REAR FENDER INNER TRIM BOARD -RH & LH	Deformed / Torn	559.60 FL	*559.60 FL
22	1		*REAR FENDER INNER TRIM BOARD CLIPS (16 PCS)	Necessary	154.80 FS	*50.00 FS
23	1		*REAR BUMPER FASCIA	Missing	381.85 FL	*381.85 FL
24	2		*REAR BUMPER SIDE RETAINER	Cracked	107.10 FL	*107.10 FL
25	2		*REAR BUMPER SIDE ATTACHMENT	Cracked	87.80 FL	*87.80 FL
26	2		*REAR BUMPER STAY -RH & LH	Bent	102.20 FL	*102.20 FL
27	4		*REAR BUMPER CENTER MOULDING SCREW	Not Necessary	51.60 FL	*- FL
28	1		*SET REAR BUMPER CLIPS	Necessary	129.00 FL	*50.00 FL
29	2		*TAIL LAMP	Cracked	567.40 FL	*567.40 FL
30	2		*TAIL LAMP SEALANT	Not Necessary	100.00 FL	*- FL
31	2		*TAIL LAMP CLIPS	Not Necessary	25.80 FL	*- FL
32	2		*TAIL LAMP LOWER PANEL -RH & LH	Bent	161.40 FL	*161.40 FL
33	8		*TAIL LAMP LOWER PANEL RIVERTS	Necessary	103.20 FL	*40.00 FL
34	1		*TAIL LAMP BASE PANEL -LH	Dented	381.80 FL	*381.80 FL
35	1		*REAR END PANEL	Badly Dented	581.95 FL	*581.95 FL
36	1		*REAR END PANEL TOP TRIM	Twisted	5.70 FL	*5.70 FL
37	4		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	51.60 FL	*- FL
38	1		*REAR FLOOR PANEL	Crumpled / Buckled	980.40 FL	*980.40 FL
39	1		*REAR FLOOR SIDE PANEL -LH	Badly Dented	182.25 FL	*182.25 FL
40	1		*REAR FLOOR PANEL INSULATOR CLOTH	Necessary	286.35 FS	*100.00 FS
41	1		*REAR FLOOR PANEL BOARD (CENTER)	Torn	591.45 FL	*316.00 FL
42	1		*REAR FLOOR PANEL SIDE BOARD -LH	Not Necessary	131.25 FL	*- FL
43	1		*REAR SUB CHASSIS MEMBER -LH	Repair	591.80 FL	*- FL
44	1		*REAR WHEEL HOUSING PANEL (OUTER) -LH	Repair	591.25 FL	*- FL
45	1		*EXHAUST SILENCER	Repair	794.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*EXHAUST SILENCER HEATER SHIELD	Bent	121.25 FL	*121.25 FL
47	3		*EXHAUST SILENCER HOOK	Not Necessary	191.70 FL	*- FL
48	1		*EXHAUST SILENCER GASKET	Not Necessary	61.10 FL	*- FL
49	1		*EXHAUST CENTER PIPE	Repair	1,218.80 FL	*- FL
50	1		*EXHAUST CENTER PIPE GASKET	Not Necessary	61.10 FL	*- FL
51	2		*EXHAUST CENTER PIPE HOOK	Not Necessary	127.80 FL	*- FL
52	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	189.70 FL	*189.70 FL
53	1		*FRONT BUMPER FASCIA	Deformed / Torn	389.95 FL	*389.95 FL
54	1		*FRONT BUMPER REINFORCEMENT	Bent	281.70 FL	*281.70 FL
55	2		*FRONT BUMPER SIDE RETAINER	Bent	87.40 FL	*87.40 FL
56	1		*SET FRONT BUMPER CLIPS	Necessary	129.00 FL	*50.00 FL
57	1		*FOG LAMP COVER	Not Necessary	161.20 FL	*- FL
58	1		*FRONT GRILLE	Cracked	287.70 FL	*287.70 FL
59	2		*FRONT GRILLE CLIPS	Not Necessary	25.80 FL	*- FL
60	1		*FRONT GRILLE BADGE	Necessary	61.50 FL	*61.50 FL
61	2		*HEAD LAMP ASSY	Holder Cracked	762.80 FL	*762.80 FL
62	1		*BONNET LOCK	Serviceable	182.10 FL	*- FL
63	1		*BONNET LOCK BRACE PANEL	Twisted	191.10 FL	*191.10 FL
64	1		*FRONT NUMBER PLATE }	Cracked	45.00 FS	*40.00 FS
65	1		*FRONT NUMBER PLATE CASING }		29.00 FS	*- FS
66	1		*FRONT BUMPER LOWER SPOILER	Not fitted	380.00 FS	*- FS
67	1		*REVERSE SENSOR	Torn / Missing	380.00 FS	*200.00 FS
68	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
69	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,471.15	10,753.95
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,021.50	2,573.49
Total Parts (\$\$)	13,449.65	8,180.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING-KING DOLLY	New	120.00	100.00
2	TO CHECK & RECONNECT SNAP WIRING	New	200.00	30.00
3	TO TUFF COAT AFFECTED AREAS	New	220.00	120.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	180.00	80.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	150.00	50.00
6	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	380.00	0.00
7	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	200.00	120.00
8	TO REMOVE & REFIX FUEL TANK	New	180.00	60.00
9	TO RESPRAY AFFECTED AREAS	New	2,200.00	1,800.00
10	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR FRONT SUPPORT PANEL BONNET ,FRONT FENDER ,REAR FENDER ,REAR CHASSIS MEMBER AND ALIGNED ALL PARTS	New	2,500.00	2,000.00
Gross Labour Cost (S\$)			6,330.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >