

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22008014/KVY3Q2**Date:** 05/10/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLM2830Y **Insured Vehicle No :** SFT1169P

Date of Loss: 13/07/2022 Nature of Claim: TP Claim No: DMPC2200293H.02/SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM2830Y**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: FB25Y458360

Reg. Date: 27/03/2017 (Man. Year: 2016) Chassis No: JF2BS9KC2GG043086

Colour: Metallic Silver Odometer: 81207 km

Engine Capacity: 2498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,831.72	499.20	1,332.52	72.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	500.00	1,540.00	75.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,871.72	999.20	2,872.52	74.19
Approved Total (Overridden) (S\$)		800.00		
(S\$)	3,871.72	800.00	3,071.72	79.34
+ GST 7.00/7.00% (S\$)	271.02	56.00	215.02	79.34
Nett Amount (S\$)	4,142.74	856.00	3,286.74	79.34

INSPECTION

Date of Assignment: 22/08/2022

Date Inspected: 26/08/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Oct 2022)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM2830Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	595.00 F	*595.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	36.00 F	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	29.00 F	*29.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	396.00 F	*- FL
5	1		*REAR END PANEL	Repair	259.20 F	*- FL
6	1		*SET REVERSE SENSOR	Serviceable	350.00 F	*- FL
					Sub Total (S\$)	1,665.20 624.00
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00 124.80
					+ Margin on L,N Items 10.00/0.00% (S\$)	166.52 0.00
					Total Parts (S\$)	1,831.72 499.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA ,TO REMOVE & REFIT DAMAGE PARTS	New	700.00	200.00
2	TO PUTTY & RESPRAY ,REAR BUMPER ,REAR END PANEL AND AFFECTED AREA	New	960.00	300.00
3	TO TUFF COAT	New	380.00	0.00
Gross Labour Cost (\$\$)			2,040.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >