3/8/23, 4:17 PM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22008021/GQY3Q2 Our File No:

08/03/2023 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00028882201

**Claimant Vehicle** 

**SNE3006Y** 

Insured

**GBK3034B** 

No:

Vehicle No:

Date of Loss:

19/08/2022

Nature of Claim: TP

Claim No:

SNM22D205856/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SNE3006Y** Reg No:

TOYOTA NOAH HYBRID, 1.8 X CVT (A) 2ZR2P10990 Make & Model: Engine No: Reg. Date: 01/03/2022 (Man. Year: 2021) Chassis No: ZWR800522795 Colour: White Odometer: 28589 km

**Engine Capacity:** 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

**Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Rear Left Side: Front Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,778.92	3,913.84	865.08	18.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	1,120.00	320.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,218.92	5,033.84	1,185.08	19.06
+ GST 8.00/8.00% (S\$)	497.51	402.71	94.80	19.05
Nett Amount (S\$)	6,716.43	5,436.55	1,279.88	19.06

**INSPECTION** 

Date of Assignment: 22/08/2022

Vin's Motor Pte Ltd (Sin Ming)

Date Inspected: 23/08/2022 Inspected At: 160 Sin Ming Drive, #03-03, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 4.0 days

XING GUO QIANG SHIAU CHAN Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/8/23, 4:17 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Mar 2023)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNE3006Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

Amount	Repairer's	Condition	Particulars	Qty Part No	. Qty	No.
1,812.00 FL	1,919.30 FL	Buckled	*REAR TAILGATE	1	1	1
*468.72 FL	495.40 FL	Cut	*REAR TAILGATE LOCK	1	1	2
*394.70 FL	394.70 FL	Twisted	*REAR TAILGATE RUBBER	1	1	3
*50.80 FL	50.80 FL	Necessary	*REAR TAILGATE HYBRID SYNERGY DRIVE NAMEPLATE	1	1	4
*573.60 FL	573.60 FL	Deformed	*REAR BUMPER	1	1	5
*30.00 FL	45.00 FL	Necessary	*REAR BUMPER CLIPS	10	10	6
*- FL	779.40 FL	Repair	*REAR END PANEL	1	1	7
*134.20 FL	134.20 FL	Necessary	*WINDSCREEN MOULDING	1	1	8
*50.00 FS	80.00 FS	Necessary	*WINDSCREEN GUM	1	1	9
*280.10 FL	280.10 FL	Deformed	*REAR END PANEL TOP TRIM	1	1	10
1,141.00 FL	1,219.40 FL	Broken	*REAR SPARE TYRE PANEL TOP COVER	1	1	11
*200.00 FS	280.00 FS	Damaged	*REVERSE SENSOR	1	1	12
		_	Nett. L=ListItemDisc.	nchise part. S=Sp	ranchise	F=Fra
5,135.12	6,251.90	Sub Total (S\$)				
1,221.28	1,472.98	- List Item Discount on L Items 25.00/25.00% (S\$)				
3,913.84	4,778.92	Total Parts (S\$)				
_	<u>,                                      </u>	=				

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIX TAILGATE GLASS	New	180.00	120.00
2	TO REPAIR DAMAGES	New	480.00	400.00
3	TO SPRAY PAINTING	New	780.00	600.00
		Gross Labour Cost (S\$)	1,440.00	1,120.00
	Report was uns	submitted during this print-out.		

< END OF ESTIMATES >